

















































MAZDA

<p>2 1.2</p> <p> Hatchback From 04/2003 To c.c. 1242 Kw. 55 Hp. 75</p> <p>(KAT)</p>	 <p>14.5007 C20140500 1141303</p> <p>14.7014 1140460 1207458</p> <p>ART2864</p>
<p>2 1.4 CD</p> <p> Hatchback From 04/2003 To c.c. 1399 Kw. 50 Hp. 68</p> <p>(KAT)</p>	 <p>14.4013 1100449</p> <p>14.5010 1221226</p> <p>14.7062 1151165 1353243 1317008</p> <p>ART2865</p>
<p>2 1.6</p> <p> Hatchback From 04/2003 To c.c. 1596 Kw. 74 Hp. 100</p> <p>(KAT)</p>	 <p>14.6097 1146860</p> <p>14.7062 1151165 1353243 1317008</p> <p>ART2866</p>
<p>121 1.1 - 1.3</p> <p> Hatchback From 10/1987 To 10/1990 c.c. 1139-1324 Kw. 40-42-44 Hp. 55-57-60</p>	 <p>20.1006 B30540500A</p> <p>20.6009 B10240300B</p> <p>20.7029 B10240100B</p> <p>ART1482</p>
<p>121 1.2 i 16V</p> <p> Hatchback From 08/1995 To 01/2002 c.c. 1242 Kw. 55 Hp. 75</p> <p>(KAT)</p>	 <p>20.0007 1E0520500</p> <p>14.6077 1E0340300</p> <p>14.7061 1E0340500</p> <p>ART1483</p>











 <p>20.1007 B35240500B</p> <p>20.0010 B3C920600B</p> <p>20.6010 B35240600C</p> <p>20.7010 B52140100E</p> <p>ART1484</p>	<p>121</p> <p>1.3 16V</p> <p> Saloon</p> <p>From 11/1990 To 03/1996</p> <p>c.c. 1324</p> <p>Kw. 53</p> <p>Hp. 72</p> <p>KAT</p>
 <p>20.0008 1E0320500A</p> <p>14.6077 1E0340300</p> <p>14.7061 1E0340500</p> <p>ART1485</p>	<p>121</p> <p>1.3</p> <p> Hatchback</p> <p>From 01/1996 To 2000</p> <p>c.c. 1299</p> <p>Kw. 44</p> <p>Hp. 60</p> <p>KAT</p>
 <p>20.0009 1E0720500</p> <p>14.6078 1E0740300</p> <p>14.7063 1E0740500</p> <p>ART1486</p>	<p>121</p> <p>1.8 D</p> <p> Hatchback</p> <p>From 01/1996 To 2000</p> <p>c.c. 1753</p> <p>Kw. 44</p> <p>Hp. 60</p> <p>KAT</p>
 <p>20.1002 BP0440500</p> <p>20.0002 B38620600A</p> <p>20.6005 BP0140300</p> <p>20.7002 B69340100E</p> <p>ART1517</p>	<p>323</p> <p>1.3 16V</p> <p> Saloon</p> <p>From 08/1989 To 07/1994</p> <p>c.c. 1324</p> <p>Kw. 49</p> <p>Hp. 67</p> <p>KAT</p>
 <p>20.1003 BP0440500D</p> <p>20.0002 B38620600A</p> <p>20.6018 B37940300</p> <p>20.7018 Z52040100A</p> <p>ART1518</p>	<p>323</p> <p>1.3 16V</p> <p> Saloon</p> <p>From 08/1994 To 09/1996</p> <p>c.c. 1324</p> <p>Kw. 54</p> <p>Hp. 73</p> <p>KAT</p>

















MAZDA

<p>323 1.3 - 1.6</p> <p> Hatchback From 09/1989 To 02/1991 c.c. 1324-1598 Kw. 49-62 Hp. 67-84</p>	 <p>20.1001 B33740500B</p> <p>20.6001 B33840300A</p> <p>20.7003 B69240100G B69240100E B69240100G9A</p> <p>ART1487</p>
<p>323 1.3 - 1.6</p> <p> Saloon From 09/1989 To 06/1991 c.c. 1324-1598 Kw. 49-62 Hp. 67-84</p>	 <p>20.1001 B33740500B</p> <p>20.6002 B33740300A</p> <p>20.7002 B69340100E</p> <p>ART1501</p>
<p>323 1.3 - 1.6 - 1.6 16V</p> <p> Hatchback From 09/1989 To 10/1994 c.c. 1324-1598 Kw. 49-62-65 Hp. 67-84-88</p> <p>(KAT)</p>	 <p>20.1002 B32240500</p> <p>20.0001 B38320600G</p> <p>20.6003 B69140300</p> <p>20.7003 BP0540100G B69240100E</p> <p>ART1512</p>
<p>323 1.3 i 16V</p> <p> Hatchback From 05/1998 To c.c. 1324 Kw. 53 Hp. 72</p> <p>(KAT)</p>	 <p>20.1017 ZL0640500</p> <p>20.0017 ZL0520600A</p> <p>20.6019 B3D540300A</p> <p>20.7020 B3D640100A</p> <p>ART1502</p>
<p>323 1.3 i 16V</p> <p> Saloon From 05/1998 To c.c. 1324 Kw. 53 Hp. 72</p> <p>(KAT)</p>	 <p>20.1017 ZL0640500</p> <p>20.0017 ZL0520600A</p> <p>20.6019 B3D540300A</p> <p>20.7017 B3D340100C</p> <p>ART1503</p>














 <p>20.1009 B37840500</p> <p>20.0011 Z50920600B</p> <p>20.6011 BZ7840300A</p> <p>20.7009 B37840100 Z53340100B</p> <p>ART1519</p>	<p>323 </p> <p>1.5 16V</p> <p> </p> <p>Hatchback-Coupe From 08/1994 To 09/1996 c.c. 1489 Kw. 65 Hp. 88</p>
 <p>20.1010 Z50540500A</p> <p>20.0011 Z50920600B</p> <p>20.6011 Z50840300A</p> <p>20.7009 B37840100</p> <p>ART1520</p>	<p>323 </p> <p>1.5 16V</p> <p> </p> <p>Hatchback-Coupe From 08/1994 To 09/1996 c.c. 1489 Kw. 65 Hp. 88</p>
 <p>20.1008 BP8940500A</p> <p>20.0011 Z53720600B</p> <p>20.6012 Z53540300</p> <p>20.7011 B39440100 Z53340100A</p> <p>ART1521</p>	<p>323 F </p> <p>1.5 16V</p> <p> </p> <p>Hatchback-5P From 10/1996 To 04/1998 c.c. 1489 Kw. 65 Hp. 88</p>
 <p>20.1017 ZL0640500</p> <p>20.0017 ZL0520600A</p> <p>20.6019 B3D540300A</p> <p>20.7020 B3D640100A</p> <p>ART1504</p>	<p>323 </p> <p>1.5 i 16V</p> <p></p> <p>Hatchback From 05/1998 To c.c. 1489 Kw. 65 Hp. 88</p>
 <p>20.1017 ZL0640500</p> <p>20.0017 ZL0520600A</p> <p>20.6019 B3D540300A</p> <p>20.7017 B3D340100C</p> <p>ART1505</p>	<p>323 </p> <p>1.5 i 16V</p> <p></p> <p>Saloon From 05/1998 To c.c. 1489 Kw. 65 Hp. 88</p>













MAZDA

<p>323 (KAT)</p> <p>1.6 16V</p> <p> Hatchback</p> <p>From 09/1989 To 10/1994</p> <p>c.c. 1598 Kw. 62-65 Hp. 84-88</p>	 <p>20.1003 BP0440500A</p> <p>20.0003 B61520600D</p> <p>20.6003 B69140300</p> <p>20.7003 BP0540100G</p> <p style="text-align: right;">ART1522</p>
<p>323 F (KAT)</p> <p>1.6 16V</p> <p> Hatchback-5P</p> <p>From 08/1989 To 07/1994</p> <p>c.c. 1598 Kw. 65 Hp. 88</p>	 <p>20.1003 BP0440500A</p> <p>20.0003 B61520600D</p> <p>20.6005 BP0140300</p> <p>20.7003 BP0540100G</p> <p style="text-align: right;">ART1523</p>
<p>323 (KAT)</p> <p>1.6 16V</p> <p> Saloon</p> <p>From 08/1989 To 07/1994</p> <p>c.c. 1598 Kw. 65 Hp. 88</p>	 <p>20.1003 BP0440500A</p> <p>20.0003 B61520600D</p> <p>20.6005 BP0140300</p> <p>20.7002 BP0240100G</p> <p style="text-align: right;">ART1524</p>
<p>323 (KAT)</p> <p>1.6 i.e. 16V</p> <p> Hatchback</p> <p>From 10/2000 To</p> <p>c.c. 1598 Kw. 72 Hp. 98</p>	 <p>20.0018 ZM412050X</p> <p>20.1018 ZM0140500A</p> <p>20.3001 ZM1140550</p> <p>20.6020 ZM1140300</p> <p>20.7021 FP3340100C</p> <p style="text-align: right;">ART1506</p>
<p>323 (KAT)</p> <p>1.6 i.e. 16V</p> <p> Saloon</p> <p>From 10/2000 To</p> <p>c.c. 1598 Kw. 72 Hp. 98</p>	 <p>20.0018 ZM412050X</p> <p>20.1018 ZM0140500A</p> <p>20.3001 ZM1140550</p> <p>20.6020 ZM1140300</p> <p>20.7022 FP3240100A</p> <p style="text-align: right;">ART1507</p>











 <p>20.1003 BP0440500A</p> <p>20.0004 BP1920600F</p> <p>20.6005 BP0140300</p> <p>20.7005 BP3340100E</p> <p>ART1488</p>	<p>323 F </p> <p>1.8 16V GT</p> <p> </p> <p>Hatchback-5P</p> <p>From 09/1989 To 03/1993</p> <p>c.c. 1840</p> <p>Kw. 94</p> <p>Hp. 128</p>
 <p>20.1003 BP0440500A</p> <p>20.0004 BP1920600F</p> <p>20.6005 BP0140300</p> <p>20.7002 BP0240100G</p> <p>ART1525</p>	<p>323 </p> <p>1.8 16V</p> <p></p> <p>Saloon</p> <p>From 08/1989 To 07/1994</p> <p>c.c. 1840</p> <p>Kw. 76</p> <p>Hp. 103</p>
 <p>20.1003 BP0440500A</p> <p>20.0004 BP1920600F</p> <p>20.6005 BP0340300</p> <p>20.7006 B68540100L</p> <p>ART1489</p>	<p>323 F </p> <p>1.8 16V</p> <p></p> <p>Hatchback</p> <p>From 08/1989 To 07/1994</p> <p>c.c. 1840</p> <p>Kw. 76-94</p> <p>Hp. 103-128</p>
 <p>20.1008 BP8940500</p> <p>20.0012 BPM620600</p> <p>20.6013 BP9840300A</p> <p>20.7019 BP8740100</p> <p>ART1490</p>	<p>323 </p> <p>1.8 16V</p> <p></p> <p>Coupe</p> <p>From 08/1994 To 09/1996</p> <p>c.c. 1840</p> <p>Kw. 84</p> <p>Hp. 114</p>
 <p>20.1011 BP8540500</p> <p>20.0012 BPM720600</p> <p>20.6014 BP5740300B</p> <p>20.7019 BP8740100</p> <p>ART1491</p>	<p>323 </p> <p>1.8 16V</p> <p></p> <p>Hatchback</p> <p>From 08/1994 To 09/1996</p> <p>c.c. 1840</p> <p>Kw. 84</p> <p>Hp. 114</p>


MAZDA

323 F 1.8 16V   Hatchback-5P From 08/1994 To 09/1996 c.c. 1840 Kw. 84 Hp. 114	<div style="text-align: right;">(KAT)</div>  <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> 20.1011 <small>BP8540500</small> </div> <div style="text-align: center;"> 20.0012 <small>BPM620600</small> </div> <div style="text-align: center;"> 20.6013 <small>BP9840300A</small> </div> <div style="text-align: center;"> 20.7019 <small>BP8740100</small> </div> </div> <div style="text-align: right;">ART1492</div>
323 1.8 i.e 16V  Hatchback From 05/1998 To c.c. 1840 Kw. 84 Hp. 114	<div style="text-align: right;">(KAT)</div>  <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> 20.1019 <small>FP3240500A</small> </div> <div style="text-align: center;"> 20.0019 <small>FP352055XB</small> <small>ø48</small> </div> <div style="text-align: center;"> 20.6021 </div> <div style="text-align: center;"> 20.7021 <small>FP3340100A</small> </div> </div> <div style="text-align: right;">ART1508</div>
323 1.8 i.e 16V  Saloon From 05/1998 To c.c. 1840 Kw. 84 Hp. 114	<div style="text-align: right;">(KAT)</div>  <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> 20.1019 <small>FP3240500A</small> </div> <div style="text-align: center;"> 20.0019 <small>FP352055XB</small> <small>ø48</small> </div> <div style="text-align: center;"> 20.6021 </div> <div style="text-align: center;"> 20.7022 <small>FP3240100A</small> </div> </div> <div style="text-align: right;">ART1509</div>
323 F 2.0 24V   Hatchback-5P From 08/1994 To 09/1998 c.c. 1995 Kw. 106 Hp. 144	<div style="text-align: right;">(KAT)</div>  <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> 20.1012 <small>KF3540500</small> </div> <div style="text-align: center;"> 20.0014 <small>KF4020600A</small> </div> <div style="text-align: center;"> 20.6015 <small>KF1640300A</small> </div> <div style="text-align: center;"> 20.7013 <small>KF1640100B</small> </div> </div> <div style="text-align: right;">ART1493</div>
323 2.0 TD   Hatchback-Coupe From 05/1998 To c.c. 1998 Kw. 66 Hp. 90	<div style="text-align: right;">(KAT)</div>  <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> 20.1020 <small>RFA540500B</small> </div> <div style="text-align: center;"> 20.4001 <small>RFA540550B</small> </div> <div style="text-align: center;"> 20.0020 <small>RF3F2060XB</small> </div> <div style="text-align: center;"> 20.7023 <small>RFA640100A</small> </div> </div> <div style="text-align: right;">ART1510</div>

 <p>20.1020 RFA540500B</p> <p>20.4001 RFA540550B</p> <p>20.0020 RF3F2060XB</p> <p>20.7024 RFA540100A</p> <p>ART1511</p>	<p>323</p> <p>2.0 TD</p> <p> Saloon</p> <p>From 05/1998 To</p> <p>c.c. 1998 Kw. 66 Hp. 90</p> <p>KAT</p>
 <p>20.1013 F81640500A</p> <p>20.0015 FEB940300A</p> <p>20.6016 FEC8400A</p> <p>20.5001 F82040600B</p> <p>20.7014 FEC1040100D</p> <p>ART1494</p>	<p>626</p> <p>1.8</p> <p>  Saloon-Hatchback</p> <p>From 11/1987 To 05/1992</p> <p>c.c. 1789 Kw. 65 Hp. 88</p> <p>KAT</p>
 <p>20.1014 FP0140500A</p> <p>20.0006 FS6320600</p> <p>20.6008 FS0540300A</p> <p>20.7008 FS0840100A</p> <p>ART1495</p>	<p>626</p> <p>1.8 i</p> <p>  Saloon-Hatchback</p> <p>From 08/1991 To 04/1997</p> <p>c.c. 1840 Kw. 77 Hp. 105</p> <p>KAT</p>
 <p>20.1015 FP1040500</p> <p>20.0006 FS6320600</p> <p>20.6008 FS0540300D</p> <p>20.7008 FS0840100A</p> <p>ART1496</p>	<p>626</p> <p>1.8 i 16V</p> <p> Saloon</p> <p>From 1991 To 1997</p> <p>c.c. 1840 Kw. 66 Hp. 90</p> <p>KAT</p>
 <p>20.1021 FP2440500B</p> <p>20.0021 FP3320600E</p> <p>20.6022 FS9040300A FP2840300A</p> <p>20.7025 FP2440100A</p> <p>ART1513</p>	<p>626</p> <p>1.8 i 16V</p> <p> Saloon</p> <p>From 04/1997 To 2003</p> <p>c.c. 1840 Kw. 66 Hp. 90</p> <p>KAT</p>

MAZDA

<p>626 (KAT)</p> <p>1.8 i 16V</p> <p> Stationwagon From 04/1997 To 2003 c.c. 1840 Kw. 66 Hp. 90</p>	 <div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;"> 20.1021 FP2440500B </div> <div style="text-align: center;"> 20.0021 FP3320600E </div> <div style="text-align: center;"> 20.6023 FS9940300 FP2740300A </div> <div style="text-align: center;"> 20.7026 FP2740100A </div> </div> <p style="text-align: right;">ART1514</p>
<p>626 (KAT)</p> <p>2.0 16V</p> <p> Saloon From 07/1987 To 05/1992 c.c. 1998 Kw. 103-109 Hp. 140-148</p>	 <div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;"> 20.1004 FEC440500C </div> <div style="text-align: center;"> 20.0005 FEC440300A </div> <div style="text-align: center;"> 20.6007 FEC340400A </div> <div style="text-align: center;"> 20.5001 F82040600B </div> <div style="text-align: center;"> 20.7015 FEC440100A </div> </div> <p style="text-align: right;">ART1497</p>
<p>626 (KAT)</p> <p>2.0 12V</p> <p> Saloon From 09/1987 To 05/1992 c.c. 1998 Kw. 79 Hp. 107</p>	 <div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;"> 20.1016 FE4640500C </div> <div style="text-align: center;"> 20.0005 FEC840300A </div> <div style="text-align: center;"> 20.6007 FEC840400A </div> <div style="text-align: center;"> 20.5001 F82040600B </div> <div style="text-align: center;"> 20.7007 FEC140100B </div> </div> <p style="text-align: right;">ART1498</p>
<p>626 (KAT)</p> <p>2.0 i</p> <p> Saloon From 08/1991 To 04/1997 c.c. 1991 Kw. 85 Hp. 115</p>	 <div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;"> 20.1005 FS0540500A </div> <div style="text-align: center;"> 20.0006 FS0520600 </div> <div style="text-align: center;"> 20.6008 FS0540300D </div> <div style="text-align: center;"> 20.7008 FS0840100A </div> </div> <p style="text-align: right;">ART1499</p>
<p>626 (KAT)</p> <p>2.0</p> <p> Hatchback From 05/1997 To 10/2002 c.c. 1991 Kw. 85 Hp. 115</p>	 <div style="display: flex; justify-content: space-around; align-items: flex-end;"> <div style="text-align: center;"> 20.1022 FS8940500B </div> <div style="text-align: center;"> 20.0021 FP3320600E </div> <div style="text-align: center;"> 20.6022 FS9040300A FP2840300A </div> <div style="text-align: center;"> 20.7027 FS9040100A </div> </div> <p style="text-align: right;">ART1515</p>




20.1022
FS8940500B

20.0021
FP3320600E

20.6023
FS9940300
FP2740300A

20.7028
FS9040100

626
2.0

**Saloon-Stationwagon**
From 05/1997 To 10/2002
c.c. 1991
Kw. 85-100
Hp. 115-116-136

