





<p><b>48.1016</b> 59113800 59113900</p> <p><b>48.8002</b> 0059114807 0059129407</p> <p>ART2404</p>	<p><b>HORIZON</b> <b>1.1 -1.3 -1.4 -1.6</b></p> <p> Hatchback From 02/1978 To 06/1986 <b>c.c.</b> 1118-1294-1424-1592 <b>Kw.</b> 40-50-61-66 <b>Hp.</b> 54-68-83-90</p>
<p><b>36.1004</b> 170290 9150246280</p> <p><b>48.6001</b> 9750073980</p> <p><b>36.7008</b> 9150995880 172598</p> <p>ART2402</p>	<p><b>SAMBA</b> <b>0.9</b></p> <p> Hatchback From 01/1981 To 12/1985 <b>c.c.</b> 947 <b>Kw.</b> 31 <b>Hp.</b> 42</p>
<p><b>36.1002</b> 9750817880 170309</p> <p><b>36.7002</b> 9750817980 172503</p> <p>ART2406</p>	<p><b>SAMBA</b> <b>1.1</b></p> <p> Hatchback From 08/1980 To 12/1985 <b>c.c.</b> 1124 <b>Kw.</b> 37 <b>Hp.</b> 50</p>
<p><b>10.1005</b> 9150246180 170291 170263</p> <p><b>36.6006</b> 9750453880</p> <p><b>36.7006</b> 9750462980 - 172483 172479 - 172407</p> <p>ART2407</p>	<p><b>SAMBA</b> <b>1.4</b></p> <p> Hatchback  Coupe From 10/1981 To 07/1982 <b>c.c.</b> 1351-1360 <b>Kw.</b> 53 <b>Hp.</b> 72</p>
<p><b>10.1007</b> 9750993280 170329</p> <p><b>36.6008</b> 9750993780</p> <p><b>36.7007</b> 9751111580 172577 172587</p> <p>ART2408</p>	<p><b>SAMBA</b> <b>1.4</b></p> <p> Hatchback From 07/1982 To 10/1986 <b>c.c.</b> 1351 <b>Kw.</b> 58 <b>Hp.</b> 79</p>

# TALBOT

<div><div>SIMCA</div><div>1.1</div><div><div>From 1971</div><div>To 1972</div></div><div><div>c.c. 1204</div><div>Kw. 55</div><div>Hp. 75</div></div></div>	<div><div><div>48.4001</div><div>44758M</div><div>0012945200</div></div><div><div><div><div>ø40</div><div>ø40</div><div>ø40</div><div>ø40</div></div></div><div><div>48.1006</div><div>38605F</div></div><div><div>48.4001</div><div>44758M</div><div>0012945200</div></div><div><div>48.5002</div><div>37309D</div><div>19110100</div></div><div><div>48.7005</div><div>33547P</div><div>19409507</div></div></div><div>ART2410</div></div>
<div><div>SIMCA</div><div>1.1</div><div><div>From 10/1976</div><div>To 09/1979</div></div><div><div>c.c. 1118</div><div>Kw. 44</div><div>Hp. 60</div></div></div>	<div><div><div><div>ø40</div><div>ø40</div></div><div><div>48.1007</div><div>16619700</div></div><div><div>48.5003</div><div>19423800</div></div><div><div>48.7006</div><div>19423907</div></div></div><div>ART2411</div></div>
<div><div>SIMCA</div><div>1.1</div><div><div>From 10/1976</div><div>To 01/1980</div></div><div><div>c.c. 1118</div><div>Kw. 43</div><div>Hp. 58</div></div></div>	<div><div><div><div>ø40</div><div>ø40</div></div><div><div>48.1005</div><div>32081F</div><div>12835100</div></div><div><div>48.4001</div><div>33005L</div><div>38685X</div></div><div><div>48.5001</div><div>33006M</div><div>13183600</div></div><div><div>48.7005</div><div>33547P</div><div>19409507</div></div></div><div>ART2409</div></div>
<div><div>SIMCA RANCH</div><div>1.4</div><div><div>From 01/1977</div><div>To 07/1984</div></div><div><div>c.c. 1442</div><div>Kw. 59</div><div>Hp. 80</div></div></div>	<div><div><div><div>ø40</div><div>ø40</div></div><div><div>48.1009</div><div>19424600</div></div><div><div>48.7007</div><div>19423207</div></div></div><div>ART2412</div></div>
<div><div>SIMCA</div><div>1.4 1307 - 1308</div><div><div>From 11/1978</div><div>To 08/1981</div></div><div><div>c.c. 1424</div><div>Kw. 63</div><div>Hp. 86</div></div></div>	<div><div><div><div>ø40</div><div>ø40</div></div><div><div>48.1012</div><div>0049110600</div></div><div><div>48.4001</div><div>44758M</div></div><div><div>48.8001</div><div>0049309007</div><div>172592</div></div></div><div>ART2403</div></div>

 <p><b>48.1014</b> 49148900 49149100</p> <p><b>48.8001</b> 49359107</p> <p>ART2405</p>	<p><b>SOLARA</b> <b>1.3 - 1.6</b></p> <p> <b>Hatchback</b> <b>From 11/1978 To 06/1982</b> <b>c.c.</b> 1294-1592 <b>Kw.</b> 40-66 <b>Hp.</b> 55-90</p>
 <p><b>48.1010</b></p> <p><b>48.6004</b></p> <p><b>48.9001</b> 20880200</p> <p>ART2413</p>	<p><b>SUNBEAM</b> <b>1.0</b></p> <p> <b>Hatchback</b> <b>From 07/1977 To 04/1981</b> <b>c.c.</b> 917 <b>Kw.</b> 31 <b>Hp.</b> 42</p>