






































































MITSUBISHI

<p>CARISMA (KAT)</p> <p>1.6</p> <p> Hatchback</p> <p>From 03/1995 To 04/1997</p> <p>c.c. 1597</p> <p>Kw. 66</p> <p>Hp. 90</p>	 <p>30.1003 MR160801</p> <p>30.0001 MB957297</p> <p>30.6005 MR204559</p> <p>30.7011 MB957279</p> <p>ART1464</p>
<p>CARISMA (KAT)</p> <p>1.6 - 1.8</p> <p>  Saloon-Hatchback</p> <p>From 07/1995 To 05/1999</p> <p>c.c. 1597-1834</p> <p>Kw. 66-85</p> <p>Hp. 90-115</p>	 <p>30.1004 MR160802 only for 1.8</p> <p>30.0001 MB957297</p> <p>30.6006 MB957940</p> <p>30.7012 MR127069</p> <p>ART1465</p>
<p>COLT</p> <p>1.2 - 1.4</p> <p>  Hatchback-3P</p> <p>From 12/1978 To 08/1980</p> <p>c.c. 1244-1410</p> <p>Kw. 40-51</p> <p>Hp. 55-70</p>	 <p>30.2001 MB111935</p> <p>30.7001 MB111860</p> <p>ART1466</p>
<p>COLT</p> <p>1.2 - 1.4</p> <p>  Hatchback-5P</p> <p>From 12/1978 To 08/1980</p> <p>c.c. 1244-1410</p> <p>Kw. 40-51</p> <p>Hp. 55-70</p>	 <p>30.2001 MB111935</p> <p>30.7003 MB111861</p> <p>ART1472</p>
<p>COLT</p> <p>1.2 - 1.5</p> <p> Hatchback</p> <p>From 03/1984 To 05/1986</p> <p>c.c. 1198-1468</p> <p>Kw. 44-55</p> <p>Hp. 60-75</p>	 <p>30.2002 MB252236</p> <p>30.7002 MB252676</p> <p>ART1476</p>






























 <p>30.1001 MB179942</p> <p>30.6001 MB179944</p> <p>30.7004 MB179952</p> <p>ART1477</p>	<p>PAJERO 2.3 TD</p> <p> </p> <p>Jeep-3P From 12/1982 To 04/1986 c.c. 2347 Kw. 62 Hp. 84 (SWB)</p>
 <p>30.1001 MB179942</p> <p>30.6001 MB179944</p> <p>30.7005 MB577361</p> <p>ART1478</p>	<p>PAJERO 2.3 TD - 2.5 TD</p> <p> </p> <p>Jeep-3P From 09/1984 To c.c. 2347-2477 Kw. 62-70 Hp. 84-95 (SWB)</p>
 <p>30.1001 MB179942</p> <p>30.6002 MB313705</p> <p>30.7006 MB376581</p> <p>ART1480</p>	<p>PAJERO 2.3 TD - 2.5 TD</p> <p> </p> <p>Jeep-5P From 09/1984 To c.c. 2347-2477 Kw. 62-70 Hp. 84-95 (LWB)</p>
 <p>30.1002 MB611506</p> <p>30.6001 MB179944</p> <p>30.7005 MB577361</p> <p>ART1479</p>	<p>PAJERO 2.5 TD</p> <p> </p> <p>Jeep-3P From 05/1986 To 10/1989 c.c. 2477 Kw. 62 Hp. 84 (SWB)</p>
 <p>30.1002 MB611506</p> <p>30.6002 MB313705</p> <p>30.7006 MB376581</p> <p>ART1481</p>	<p>PAJERO 2.5 TD</p> <p> </p> <p>Jeep-5P From 05/1986 To 10/1989 c.c. 2477 Kw. 62 Hp. 84 (LWB)</p>











MITSUBISHI

PAJERO 2.5 TD   Jeep-3P From 11/1988 To 11/1990 c.c. 2995 Kw. 104 Hp. 141 (SWB)	 30.1002 MB611506  30.6001 MB252507 MB179944  30.7007 MB651233 MB611684  30.9001 MB611686 MB612220
PAJERO 2.5 TD   Jeep-5P From 11/1988 To 11/1990 c.c. 2477 Kw. 73 Hp. 99 (LWB)	 30.1002 MB611506  30.6002 MB313706 MB313705  30.7009 MB651234 MB577833  30.9003 MB611687
PAJERO 2.5 TD   Jeep-5P From 12/1990 To 05/1996 c.c. 2477 Kw. 73 Hp. 99 (LWB)	 30.1002 MB611506  30.6003 MB651687  30.7010 MB651689  30.9003 MB611687
PAJERO 2.5 TD   Jeep-3P From 12/1990 To 05/1996 c.c. 2477 Kw. 73 Hp. 99 (SWB)	 30.1002 MB611506  30.6003 MB651687  30.7008 MB651696 MB651688  30.9001 MB611686 MB612220
PAJERO 2.5 TDi    Jeep-3P From 05/2000 To c.c. 2477 Kw. 85 Hp. 115 (SWB)	 30.1007 MR481129  30.0003 MR597285  30.6007 MB332070 MB924360  30.7016 MR552588

 <p>30.1007 MR481129</p> <p>30.0003 MR597285</p> <p>30.6008 MR552576</p> <p>30.7017 MR552578</p> <p>ART2904</p>	<p>PAJERO</p> <p>2.5 TDi</p> <p> Jeep</p> <p>From 05/2000 To</p> <p>c.c. 2477</p> <p>Kw. 85</p> <p>Hp. 115</p> <p>(LWB)</p>
 <p>30.1006 MB924365</p> <p>30.6007 MB332070 MB924360</p> <p>30.7013 MB924369</p> <p>30.9005 MB924376</p> <p>ART1473</p>	<p>PAJERO</p> <p>2.8 TD</p> <p> Jeep-3P</p> <p>From 06/1994 To 05/1996</p> <p>c.c. 2835</p> <p>Kw. 92</p> <p>Hp. 125</p> <p>(SWB)</p>
 <p>30.1006 MB924365</p> <p>30.6007 MB332070 MB924360</p> <p>30.7015 MR187151 MR204857</p> <p>30.9006 MB924377 MB925144</p> <p>ART1471</p>	<p>PAJERO</p> <p>2.8 TD</p> <p> Jeep-5P</p> <p>From 06/1994 To 05/1996</p> <p>c.c. 2835</p> <p>Kw. 92</p> <p>Hp. 125</p> <p>(LWB)</p>
 <p>30.1006 MB924365</p> <p>30.6007 MB332070 MB924360</p> <p>30.7014 MR266476</p> <p>30.9004 MR239652</p> <p>ART1475</p>	<p>PAJERO</p> <p>2.8 TD</p> <p> Jeep-3P</p> <p>From 05/1996 To 04/2000</p> <p>c.c. 2835</p> <p>Kw. 92</p> <p>Hp. 125</p> <p>(SWB)</p>
 <p>30.1006 MB924365</p> <p>30.6007 MB332070 MB924360</p> <p>30.7015 MR187151 MR204857</p> <p>30.9007 MR239654</p> <p>ART1474</p>	<p>PAJERO</p> <p>2.8 TD</p> <p> Jeep-5P</p> <p>From 05/1996 To 04/2000</p> <p>c.c. 2835</p> <p>Kw. 92</p> <p>Hp. 125</p> <p>(LWB)</p>

MITSUBISHI

<p>PAJERO (KAT)</p> <p>3.2 DI - D</p> <p> </p> <p>Jeep-3P</p> <p>From 10/2001 To</p> <p>c.c. 3200</p> <p>Kw. 118</p> <p>Hp. 160</p> <p>(SWB)</p>	 <p>30.1008 MR552467</p>  <p>30.0002 MR968500</p>  <p>30.6009 MR597163</p>  <p>30.7018 MR481135</p> <p>ART2905</p>
<p>PAJERO (KAT)</p> <p>3.2 DI - D</p> <p> </p> <p>Jeep-5P</p> <p>From 10/2001 To</p> <p>c.c. 3200</p> <p>Kw. 118</p> <p>Hp. 160</p> <p>(LWB)</p>	 <p>30.1008 MR552467</p>  <p>30.0002 MR968500</p>  <p>30.6010 MR481153</p>  <p>30.7019 MR597164</p> <p>ART2906</p>
<p>PAJERO PININ (KAT)</p> <p>1.8 GDI</p> <p></p> <p>Jeep</p> <p>From 10/1999 To</p> <p>c.c. 1834</p> <p>Kw. 88</p> <p>Hp. 120</p>	 <p>30.1009 MR464778</p>  <p>30.0004 MR497218 MR597989</p>  <p>30.6011 MR464597</p>  <p>30.7020 MR431257</p> <p>ART2907</p>
<p>PAJERO PININ (KAT)</p> <p>1.8</p> <p> </p> <p>Jeep-3P</p> <p>From 11/2001 To</p> <p>c.c. 1834</p> <p>Kw. 84</p> <p>Hp. 114</p> <p>(SWB)</p>	 <p>30.4001 MR539027</p>  <p>30.0004 MR497218 MR597989</p>  <p>30.5001 MR968429</p>  <p>30.7020 MR431257</p> <p>ART2908</p>
<p>PAJERO PININ (KAT)</p> <p>1.8</p> <p> </p> <p>Jeep-5P</p> <p>From 11/2001 To</p> <p>c.c. 1834</p> <p>Kw. 84</p> <p>Hp. 114</p> <p>(LWB)</p>	 <p>30.4001 MR539027</p>  <p>30.0004 MR497218 MR597989</p>  <p>30.5002 MR968430</p>  <p>30.7021 MB890841</p> <p>ART2909</p>

<div>  <p>30.1009 MR464778</p> </div> <div>  <p>30.0005 MR552442</p> </div> <div>  <p>30.6012 MR431407</p> </div> <div>  <p>30.7022 MR539028</p> </div> <div>ART2910</div>	<div> PAJERO PININ <div>KAT</div> </div> <div> 2.0 GDI </div> <div> <div>  <div>3</div> </div> Jeep-3P </div> <div> From 10/2000 To </div> <div> c.c. 1999 </div> <div> Kw. 95 </div> <div> Hp. 129 </div> <div> (SWB) </div>
<div>  <p>30.1009 MR464778</p> </div> <div>  <p>30.0005 MR552442</p> </div> <div>  <p>30.6013 MR514884</p> </div> <div>  <p>30.7023 MR529442</p> </div> <div>ART2911</div>	<div> PAJERO PININ <div>KAT</div> </div> <div> 2.0 GDI </div> <div> <div>  <div>5</div> </div> Jeep-5P </div> <div> From 10/2000 To </div> <div> c.c. 1999 </div> <div> Kw. 95 </div> <div> Hp. 129 </div> <div> (LWB) </div>