

















































 <p><b>14.1076</b> 7M0253091P 7M0253091AQ</p> <p><b>58.0005</b> 6K0131701EX 6K0131701E</p> <p><b>14.6083</b> 1015985 7M0253409AA 7M0253409AQ</p> <p><b>14.7114</b> 1015984 7M0253609AS</p> <p>ART2281</p>	<p><b>ALHAMBRA</b> </p> <p><b>1.9 TDI</b></p> <p> <b>MPV</b></p> <p><b>From 03/1996 To 04/2000</b></p> <p><b>c.c.</b> 1896 <b>Kw.</b> 66 <b>Hp.</b> 90</p>
 <p><b>58.0044</b> 7271700 1022355 7M0131089BV 7M0131089BX 7M0131701SV 7M0131701SX</p> <p><b>14.6082</b> 1013486 1016964 1087573 7M0253409AT 7M0253409T</p> <p><b>14.7011</b> 7M0253609AH 7M0253609AT</p> <p>ART2280</p>	<p><b>ALHAMBRA</b> </p> <p><b>2.0 i</b></p> <p> <b>MPV</b></p> <p><b>From 09/1995 To 05/2000</b></p> <p><b>c.c.</b> 1996 <b>Kw.</b> 85 <b>Hp.</b> 115</p>
 <p><b>58.0036</b> 6N0253058BX 6N0253058MX</p> <p><b>58.6053</b> 6X0253209A 6X0253209D</p> <p><b>58.7063</b> 6X0253609A</p> <p>ART2374</p>	<p><b>AROSA</b> </p> <p><b>1.0 i</b></p> <p> <b>Hatchback</b></p> <p><b>From 05/1997 To 07/2005</b></p> <p><b>c.c.</b> 999 <b>Kw.</b> 37 <b>Hp.</b> 50 Mot. AER</p>
 <p><b>58.0037</b> 047253208EX</p> <p><b>58.6053</b> 6X0253209A</p> <p><b>58.7063</b> 6X0253609A</p> <p>ART2283</p>	<p><b>AROSA</b> </p> <p><b>1.0 i</b></p> <p> <b>Hatchback</b></p> <p><b>From 05/1997 To 07/2005</b></p> <p><b>c.c.</b> 999 <b>Kw.</b> 37 <b>Hp.</b> 50 Mot. AHT</p>
 <p><b>58.0036</b> 6N0253058BX 6N0253058MX</p> <p><b>58.6053</b> 6X0253209A</p> <p><b>58.7063</b> 6X0253609A</p> <p>ART2373</p>	<p><b>AROSA</b> </p> <p><b>1.4 i</b></p> <p> <b>Hatchback</b></p> <p><b>From 05/1997 To 07/2005</b></p> <p><b>c.c.</b> 1390 <b>Kw.</b> 44 <b>Hp.</b> 60 Mot. APQ-AEX-AKV</p>











<p><b>AROSA</b> <span style="float: right;">(KAT)</span></p> <p><b>1.4 16V</b></p> <p> Hatchback</p> <p>From 09/1998 To 07/2005</p> <p><b>c.c.</b> 1390 <b>Kw.</b> 55 <b>Hp.</b> 75</p> <p>Mot. AKQ-AHW</p>	 <p><b>58.0040</b> 6N0253058HX</p> <p><b>58.6054</b> 6X0253209B</p> <p><b>58.7064</b> 6X0253609B</p> <p style="text-align: right;">ART2372</p>
<p><b>AROSA</b> <span style="float: right;">(KAT)</span></p> <p><b>1.4 TDI</b></p> <p> Hatchback</p> <p>From 01/2000 To 07/2005</p> <p><b>c.c.</b> 1422 <b>Kw.</b> 55 <b>Hp.</b> 75</p> <p>Mot. AMF</p>	 <p><b>58.0045</b> 6X0253208KX</p> <p><b>58.6055</b> 6X0253209C</p> <p><b>58.7065</b> 6X0253609C</p> <p style="text-align: right;">ART2284</p>
<p><b>AROSA</b> <span style="float: right;">(KAT)</span></p> <p><b>1.7 SDI</b></p> <p> Hatchback</p> <p>From 08/1997 To 07/2005</p> <p><b>c.c.</b> 1716 <b>Kw.</b> 44 <b>Hp.</b> 60</p> <p>Mot. AKU</p>	 <p><b>58.0041</b> 6N0253058EX</p> <p><b>58.6055</b> 6X0253209C</p> <p><b>58.7065</b> 6X0253609C</p> <p style="text-align: right;">ART2371</p>
<p><b>CORDOBA</b> <span style="float: right;">(KAT)</span></p> <p><b>1.4 i - 1.6 i</b></p> <p> Saloon</p> <p>From 02/1993 To 06/1999</p> <p><b>c.c.</b> 1390-1598 <b>Kw.</b> 44-55 <b>Hp.</b> 60-75</p>	 <p><b>58.1042</b> 6K0253091E 1H0253091AA</p> <p><b>58.0001</b> 6K0131701H 6N0131701HX</p> <p><b>46.6013</b> 6K6253409 6K6253409H 6K6253409Q</p> <p><b>46.7015</b> 6K5253609B</p> <p style="text-align: right;">ART2336</p>
<p><b>CORDOBA</b> <span style="float: right;">(KAT)</span></p> <p><b>1.4 i</b></p> <p>  Saloon-Stationwagon</p> <p>From 12/1995 To 09/2001</p> <p><b>c.c.</b> 1390 <b>Kw.</b> 44 <b>Hp.</b> 60</p>	 <p><b>58.0029</b> 6N0131701HX</p> <p><b>46.6013</b> 6K6253409 6K6253409J 6K6253409H 6K6253409Q</p> <p><b>58.7035</b> 6K5253608H 6K5253609AE</p> <p style="text-align: right;">ART2375</p>












 <p><b>46.1019</b> 6K0253087D</p> <p><b>46.0007</b> 6K0131701AF 6K0131089X</p> <p><b>46.6014</b> 6K6253409E 6K6253409A</p> <p><b>58.7029</b> 6K5253609J</p> <p>ART2351</p>	<p><b>CORDOBA</b> </p> <p><b>1.4 i 16V</b></p> <p> <b>Saloon</b></p> <p><b>From 09/1996 To 06/1999</b></p> <p><b>c.c.</b> 1390 <b>Kw.</b> 74 <b>Hp.</b> 101</p>
 <p><b>58.1042</b> 6K0253091E</p> <p><b>58.0001</b> 6K0131701H</p> <p><b>46.6013</b> 6K6253409</p> <p><b>46.7015</b> 6K5253609B</p> <p>ART2337</p>	<p><b>CORDOBA</b> </p> <p><b>1.6 i</b></p> <p> <b>Saloon</b></p> <p><b>From 02/1993 To 06/1999</b></p> <p><b>c.c.</b> 1598 <b>Kw.</b> 55 <b>Hp.</b> 75</p>
 <p><b>58.0031</b> 6K0253085BX 6K0253085BV</p> <p><b>46.6014</b> 6K6253409E 6K6253409A</p> <p><b>58.7029</b> 6K5253609J</p> <p>ART2352</p>	<p><b>CORDOBA</b> </p> <p><b>1.6 i</b></p> <p> <b>Saloon</b></p> <p><b>From 02/1993 To 09/2001</b></p> <p><b>c.c.</b> 1595-1598 <b>Kw.</b> 55 <b>Hp.</b> 75 Mot. 1F</p>
 <p><b>46.1027</b> 6K0253087G</p> <p><b>46.0019</b> 6K0131701H 191131701D</p> <p><b>46.6022</b> 6K6253409D</p> <p><b>58.7029</b> 6K5253609AH 6K5253609J</p> <p>ART2912</p>	<p><b>CORDOBA</b> </p> <p><b>1.6 i</b></p> <p> <b>Saloon</b></p> <p><b>From 05/1997 To 08/2002</b></p> <p><b>c.c.</b> 1598 <b>Kw.</b> 55 <b>Hp.</b> 75 Mot. AEE</p>
 <p><b>46.1028</b> 6K0253087Q</p> <p><b>46.0019</b> 6K0131701H 191131701D</p> <p><b>46.6022</b> 6K6253409D</p> <p><b>58.7029</b> 6K5253609AH 6K5253609J</p> <p>ART2913</p>	<p><b>CORDOBA</b> </p> <p><b>1.6 i</b></p> <p> <b>Saloon</b></p> <p><b>From 05/1997 To 08/2002</b></p> <p><b>c.c.</b> 1598 <b>Kw.</b> 55 <b>Hp.</b> 75 Mot. ALM</p>

# SEAT











<b>CORDOBA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.8 i</b>  <b>Saloon</b> <b>From 02/1993 To 05/1995</b> <b>c.c.</b> 1781 <b>Kw.</b> 66 <b>Hp.</b> 90	 <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <b>58.1046</b>  <small>6K0253087A</small> </div> <div style="text-align: center;"> <b>58.0002</b>  <small>6K0131701J</small> </div> <div style="text-align: center;"> <b>46.6014</b>  <small>6K6253409E 6K6253409A</small> </div> <div style="text-align: center;"> <b>46.7017</b>  <small>6K5253609E</small> </div> </div> <div style="text-align: right; font-size: small;">ART2338</div>
<b>CORDOBA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.8 i</b>  <b>Saloon</b> <b>From 06/1995 To 09/2001</b> <b>c.c.</b> 1781 <b>Kw.</b> 66 <b>Hp.</b> 90	 <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <b>58.0031</b>  <small>6K0253085BX</small> </div> <div style="text-align: center;"> <b>46.6014</b>  <small>6K6253409E 6K6253409A</small> </div> <div style="text-align: center;"> <b>58.7029</b>  <small>6K5253609J</small> </div> </div> <div style="text-align: right; font-size: small;">ART2353</div>
<b>CORDOBA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.9 D</b>  <b>Saloon</b> <b>From 02/1993 To 08/1996</b> <b>c.c.</b> 1896 <b>Kw.</b> 48 <b>Hp.</b> 65	 <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <b>58.1033</b>  <small>6K0253091H</small> </div> <div style="text-align: center;"> <b>58.0004</b>  <small>6K0131701LX</small> </div> <div style="text-align: center;"> <b>46.6013</b>  <small>6K6253409</small> </div> <div style="text-align: center;"> <b>46.7015</b>  <small>6K5253609B</small> </div> </div> <div style="text-align: right; font-size: small;">ART2340</div>
<b>CORDOBA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.9 TD</b>  <b>Saloon</b> <b>From 07/1994 To 08/1996</b> <b>c.c.</b> 1896 <b>Kw.</b> 55 <b>Hp.</b> 75	 <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <b>58.1048</b>  <small>1H0253087B 1H0253087AC</small> </div> <div style="text-align: center;"> <b>58.0005</b>  <small>6K0131701E</small> </div> <div style="text-align: center;"> <b>46.6014</b>  <small>6K6253409A 6K6253409E</small> </div> <div style="text-align: center;"> <b>46.7017</b>  <small>6K5253609E</small> </div> </div> <div style="text-align: right; font-size: small;">ART2341</div>
<b>CORDOBA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.9 TD</b>  <b>Saloon</b> <b>From 08/1996 To 09/2001</b> <b>c.c.</b> 1896 <b>Kw.</b> 66 <b>Hp.</b> 90	 <div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <b>58.1037</b>  <small>1H0253091AC 3A0253091J</small> </div> <div style="text-align: center;"> <b>58.0005</b>  <small>6K0131701E 6K0131701EX</small> </div> <div style="text-align: center;"> <b>46.6014</b>  <small>6K6253409E 6K6253409A</small> </div> <div style="text-align: center;"> <b>46.7025</b>  <small>6K5253609L</small> </div> </div> <div style="text-align: right; font-size: small;">ART2355</div>

<p><b>58.1005</b> 6K1253091C</p> <p><b>58.0003</b> 6K0131701G</p> <p><b>46.6014</b> 6K6253409E 6K6253409A</p> <p><b>46.7017</b> 6K5253609E</p> <p>ART2339</p>	<p><b>CORDOBA</b> </p> <p><b>2.0 i</b></p> <p> Saloon</p> <p>From 02/1993 To 06/1996</p> <p><b>c.c.</b> 1984</p> <p><b>Kw.</b> 85</p> <p><b>Hp.</b> 115</p>
<p><b>58.1015</b> 6K1253091G</p> <p><b>46.0009</b> 6K0131701PX</p> <p><b>46.6021</b> 6K6253409F</p> <p><b>58.7029</b> 6K5253609J</p> <p>ART2354</p>	<p><b>CORDOBA</b> </p> <p><b>2.0 i</b></p> <p> Saloon</p> <p>From 07/1996 To 06/1999</p> <p><b>c.c.</b> 1984</p> <p><b>Kw.</b> 85</p> <p><b>Hp.</b> 115</p>
<p><b>46.1001</b> 12711503A SE3934063</p> <p><b>12.7011</b> 4277782 4297426</p> <p>ART2308</p>	<p><b>FURA</b></p> <p><b>0.9</b></p> <p> Hatchback</p> <p>From 1983 To 12/1986</p> <p><b>c.c.</b> 903</p> <p><b>Kw.</b> 29-33</p> <p><b>Hp.</b> 40-45</p>
<p><b>46.1016</b> SE021115103C</p> <p><b>46.7005</b> SE021115315B SE021115315C</p> <p>ART2309</p>	<p><b>IBIZA</b></p> <p><b>0.9</b></p> <p> Hatchback</p> <p>From 08/1986 To 06/1989</p> <p><b>c.c.</b> 903</p> <p><b>Kw.</b> 32</p> <p><b>Hp.</b> 44</p>
<p><b>46.1016</b> SE021115103C</p> <p><b>46.7006</b> SE021115315D SE021115315E</p> <p>ART2310</p>	<p><b>IBIZA</b></p> <p><b>0.9</b></p> <p> Hatchback</p> <p>From 07/1989 To 07/1992</p> <p><b>c.c.</b> 903</p> <p><b>Kw.</b> 29-32</p> <p><b>Hp.</b> 40-44</p>

























<p><b>IBIZA</b></p> <p><b>1.2</b></p> <p> Hatchback</p> <p>From 07/1984 To 12/1984</p> <p>c.c. 1193</p> <p>Kw. 44</p> <p>Hp. 60</p>	 <p><b>46.1003</b> SE021115103A</p> <p><b>46.6003</b> SE021115201A</p> <p><b>46.7005</b> SE021115315A SE021115315B</p> <p>ART2311</p>
<p><b>IBIZA</b></p> <p><b>1.2</b></p> <p> Hatchback</p> <p>From 11/1984 To 06/1989</p> <p>c.c. 1193</p> <p>Kw. 44</p> <p>Hp. 60</p>	 <p><b>46.1004</b> SE021115103B</p> <p><b>46.6004</b> SE021115201F SE021115201G</p> <p><b>46.7005</b> SE021115315A SE021115315B</p> <p>ART2313</p>
<p><b>IBIZA</b></p> <p><b>1.2</b></p> <p> Hatchback</p> <p>From 07/1989 To 07/1992</p> <p>c.c. 1193</p> <p>Kw. 44</p> <p>Hp. 60</p>	 <p><b>46.1004</b> SE021115103B</p> <p><b>46.6004</b> SE021115201F SE021115201G</p> <p><b>46.7006</b> SE021115315D</p> <p>ART2316</p>
<p><b>IBIZA</b></p> <p><b>1.5</b></p> <p> Hatchback</p> <p>From 07/1984 To 12/1984</p> <p>c.c. 1461</p> <p>Kw. 63</p> <p>Hp. 85</p>	 <p><b>46.1003</b> SE021115103A</p> <p><b>46.6003</b> SE021115201A</p> <p><b>46.7005</b> SE021115315A SE021115315B</p> <p>ART2312</p>
<p><b>IBIZA</b></p> <p><b>1.5</b></p> <p> Hatchback</p> <p>From 11/1984 To 06/1989</p> <p>c.c. 1461</p> <p>Kw. 63</p> <p>Hp. 85</p>	 <p><b>46.1004</b> SE021115103B</p> <p><b>46.6004</b> SE021115201C</p> <p><b>46.7005</b> SE021115315A SE021115315B</p> <p>ART2315</p>

 <p><b>46.1004</b> SE021115103B</p> <p><b>46.6004</b> SE021115201C SE021115201F</p> <p><b>46.7006</b> SE021115315D</p> <p>ART2317</p>	<p><b>IBIZA</b></p> <p><b>1.5</b></p> <p> Hatchback</p> <p>From 07/1989 To 07/1992</p> <p><b>c.c.</b> 1461</p> <p><b>Kw.</b> 83</p> <p><b>Hp.</b> 85</p>
 <p><b>46.2001</b> SE021115103F</p> <p><b>46.6004</b> SE021115201G</p> <p><b>46.7006</b> SE021115315E SE021115315D</p> <p>ART2318</p>	<p><b>IBIZA</b></p> <p><b>1.5 i</b></p> <p> Hatchback</p> <p>From 02/1987 To 07/1992</p> <p><b>c.c.</b> 1461</p> <p><b>Kw.</b> 74</p> <p><b>Hp.</b> 100</p>
 <p><b>46.1005</b> SE138115103A</p> <p><b>46.6005</b> SE021115201B</p> <p><b>46.7005</b> SE021115315A SE021115315B</p> <p><b>46.1008</b> ← 7 / 1986 → SE021115103D</p> <p>ART2319</p>	<p><b>IBIZA</b></p> <p><b>1.7 D</b></p> <p> Hatchback</p> <p>From 06/1984 To 06/1989</p> <p><b>c.c.</b> 1714</p> <p><b>Kw.</b> 40</p> <p><b>Hp.</b> 54</p>
 <p><b>46.1008</b> SE021115103D</p> <p><b>46.6005</b> SE021115201B</p> <p><b>46.7006</b> SE021115315D</p> <p>ART2320</p>	<p><b>IBIZA</b></p> <p><b>1.7 D</b></p> <p> Hatchback</p> <p>From 07/1989 To 05/1993</p> <p><b>c.c.</b> 1714</p> <p><b>Kw.</b> 48</p> <p><b>Hp.</b> 65</p>
 <p><b>58.1042</b> 6K0253091E</p> <p><b>58.0001</b> 6K0131701H</p> <p><b>46.6013</b> 6K6253409</p> <p><b>46.7009</b> 6K6253609</p> <p>ART2321</p>	<p><b>IBIZA II</b> </p> <p><b>1.0 i</b></p> <p> Hatchback</p> <p>From 03/1993 To 04/1996</p> <p><b>c.c.</b> 1043</p> <p><b>Kw.</b> 33</p> <p><b>Hp.</b> 45</p>







# SEAT
















<b>IBIZA II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.0 i</b>  <b>Hatchback</b> <b>From 05/1996 To 2002</b> <b>c.c.</b> 999 <b>Kw.</b> 37 <b>Hp.</b> 50	 <p> <b>46.0010</b>              6K0253058GX           </p> <p> <b>46.6013</b>              6K6253409H           </p> <p> <b>46.7026</b>              6K6253609T           </p> <p style="text-align: right;">ART2356</p>
<b>IBIZA II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.3 i</b>  <b>Hatchback</b> <b>From 03/1993 To 04/1996</b> <b>c.c.</b> 1272 <b>Kw.</b> 55 <b>Hp.</b> 75	 <p> <b>58.1042</b>              6K0253091E           </p> <p> <b>58.0001</b>              6K0131701H           </p> <p> <b>46.6013</b>              6K6253409           </p> <p> <b>46.7009</b>              6K6253609           </p> <p style="text-align: right;">ART2322</p>
<b>IBIZA II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.4 i</b>  <b>Hatchback</b> <b>From 05/1996 To 2002</b> <b>c.c.</b> 1390 <b>Kw.</b> 44 <b>Hp.</b> 60	 <p> <b>46.0011</b>              6K0253058HX           </p> <p> <b>46.6013</b>              6K6253409J           </p> <p> <b>46.7026</b>              6K6253609T           </p> <p style="text-align: right;">ART2357</p>
<b>IBIZA II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.6 i</b>  <b>Hatchback</b> <b>From 03/1993 To 08/1999</b> <b>c.c.</b> 1598 <b>Kw.</b> 55 <b>Hp.</b> 75	 <p> <b>58.1042</b>              6K0253091E           </p> <p> <b>58.0001</b>              6K0131701H           </p> <p> <b>46.6013</b>              6K6253409           </p> <p> <b>46.7009</b>              6K6253609           </p> <p style="text-align: right;">ART2324</p>
<b>IBIZA II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span> <b>1.6 i</b>  <b>Hatchback</b> <b>From 06/1995 To 2002</b> <b>c.c.</b> 1598 <b>Kw.</b> 55 <b>Hp.</b> 75 <b>Mot.</b> 1F	 <p> <b>58.0031</b>              6K0253085BV              6K0253085BX           </p> <p> <b>46.6014</b>              6K6253409E              6K6253409A           </p> <p> <b>46.7027</b>              6K6253609J              6K6253609M           </p> <p style="text-align: right;">ART2358</p>

<p><b>46.1027</b> 6K0253087G</p> <p><b>46.0019</b> 6K0131701H 191131701D 6N0131701RX 6N0131701GV</p> <p><b>46.6022</b> 6K6253409D</p> <p><b>58.7027</b> 6K6253609M 6K6253609AD</p> <p>ART2918</p>	<p><b>IBIZA II</b> </p> <p><b>1.6 i</b></p> <p> Hatchback</p> <p>From 05/1997 To 08/2002</p> <p><b>c.c.</b> 1598</p> <p><b>Kw.</b> 55</p> <p><b>Hp.</b> 75</p> <p>Mot. AEE</p>
<p><b>46.1028</b> 6K0253087Q</p> <p><b>46.0019</b> 6K0131701H 191131701D 6N0131701RX 6N0131701GV</p> <p><b>46.6022</b> 6K6253409D</p> <p><b>58.7027</b> 6K6253609M 6K6253609AD</p> <p>ART2919</p>	<p><b>IBIZA II</b> </p> <p><b>1.6 i</b></p> <p> Hatchback</p> <p>From 05/1997 To 08/2002</p> <p><b>c.c.</b> 1598</p> <p><b>Kw.</b> 55</p> <p><b>Hp.</b> 75</p> <p>Mot. ALM</p>
<p><b>58.1046</b> 6K0253087A</p> <p><b>58.0002</b> 6K0131701J</p> <p><b>46.6014</b> 6K6253409E 6K6253409A</p> <p><b>46.7011</b> 6K6253609C</p> <p>ART2325</p>	<p><b>IBIZA II</b> </p> <p><b>1.8 i</b></p> <p> Hatchback</p> <p>From 03/1993 To 05/1995</p> <p><b>c.c.</b> 1781</p> <p><b>Kw.</b> 66</p> <p><b>Hp.</b> 90</p>
<p><b>58.0031</b> 6K0253085BV 6K0253085BX</p> <p><b>46.6014</b> 6K6253409E 6K6253409A</p> <p><b>46.7027</b> 6K6253609J</p> <p>ART2360</p>	<p><b>IBIZA II</b> </p> <p><b>1.8 i</b></p> <p> Hatchback</p> <p>From 07/1996 To 2002</p> <p><b>c.c.</b> 1781</p> <p><b>Kw.</b> 66</p> <p><b>Hp.</b> 90</p>
<p><b>58.1033</b> 6K0253091H</p> <p><b>58.0004</b> 6K0131701LX</p> <p><b>46.6013</b> 6K6253409</p> <p><b>46.7009</b> 6K6253609</p> <p>ART2327</p>	<p><b>IBIZA II</b> </p> <p><b>1.9 D</b></p> <p> Hatchback</p> <p>From 04/1993 To 08/1996</p> <p><b>c.c.</b> 1896</p> <p><b>Kw.</b> 47</p> <p><b>Hp.</b> 64</p>











<b>IBIZA II</b> <b>1.9 D SDi</b>  <b>Hatchback</b> <b>From 08/1996 To 2002</b> <b>c.c.</b> 1896 <b>Kw.</b> 47 <b>Hp.</b> 64	<div>     </div> <div> <b>58.1033</b>            6K0253091H         </div> <div> <b>58.0005</b>            6K0131701E            028131701BX            028131701B            1015983            028131089X         </div> <div> <b>46.6014</b>            6K6253409E            6K6253409A         </div> <div> <b>46.7027</b>            6K6253609J         </div> <div>ART2363</div>
<b>IBIZA II</b> <b>1.9 TD</b>  <b>Hatchback</b> <b>From 07/1994 To 08/1996</b> <b>c.c.</b> 1896 <b>Kw.</b> 55 <b>Hp.</b> 75	<div>     </div> <div> <b>58.1048</b>            1H0253087AC         </div> <div> <b>58.0005</b>            6K0131701E         </div> <div> <b>46.6014</b>            6K6253409E            6K6253409A         </div> <div> <b>46.7011</b>            6K6253609C         </div> <div>ART2328</div>
<b>IBIZA II</b> <b>2.0 i GTi 16V</b>  <b>Hatchback</b> <b>From 03/1993 To 06/1996</b> <b>c.c.</b> 1984 <b>Kw.</b> 85 <b>Hp.</b> 115	<div>     </div> <div> <b>58.1005</b>            6K1253091C         </div> <div> <b>58.0003</b>            6K0131701G         </div> <div> <b>46.6014</b>            6K6253409E            6K6253409A         </div> <div> <b>46.7011</b>            6K6253609C         </div> <div>ART2326</div>
<b>IBIZA II</b> <b>2.0 i GTi 8V</b>  <b>Hatchback</b> <b>From 07/1996 To 08/1999</b> <b>c.c.</b> 1984 <b>Kw.</b> 85 <b>Hp.</b> 115	<div>     </div> <div> <b>58.1015</b>            6K1253091G         </div> <div> <b>46.0009</b>            6K0131701PX         </div> <div> <b>46.6021</b>            6K6253409K         </div> <div> <b>46.7027</b>            6K6253609S         </div> <div>ART2361</div>
<b>IBIZA III</b> <b>1.2</b>  <b>Hatchback</b> <b>From 02/2002 To</b> <b>c.c.</b> 1198 <b>Kw.</b> 47 <b>Hp.</b> 64	<div>    </div> <div> <b>50.5002</b>            6Q0253091         </div> <div> <b>50.6007</b>            6Q0253209J         </div> <div> <b>50.7019</b>            6Q6253609J         </div> <div>ART2914</div>












<p><b>50.0006</b> 6Q0254500AX 6Q0254500KX</p> <p><b>50.6005</b> 6Q0253209AA</p> <p><b>50.7015</b> 6Q6253609AA 6Q6253609</p>	<p><b>IBIZA III</b> </p> <p><b>1.4 16V</b></p> <p> Hatchback</p> <p>From 02/2002 To</p> <p><b>c.c.</b> 1390 <b>Kw.</b> 55 <b>Hp.</b> 75</p>
<p><b>50.0008</b> 6Q0254500HX</p> <p><b>50.5001</b> 6Q0253201</p> <p><b>50.7021</b> 6Q6253609T 6Q625609BE</p>	<p><b>IBIZA III</b> </p> <p><b>1.4 TDI</b></p> <p> Hatchback</p> <p>From 05/2002 To</p> <p><b>c.c.</b> 1422 <b>Kw.</b> 55 <b>Hp.</b> 75</p>
<p><b>50.0007</b> 6Q0254500MX</p> <p><b>50.6006</b> 6Q0253209D</p> <p><b>50.7017</b> 6Q6253609D</p>	<p><b>IBIZA III</b> </p> <p><b>1.9 SDI</b></p> <p> Hatchback</p> <p>From 02/2002 To</p> <p><b>c.c.</b> 1896 <b>Kw.</b> 47 <b>Hp.</b> 64</p>
<p><b>58.1041</b> 6K0253091AB 6K0253091P</p> <p><b>58.0001</b> 191131701D 6K0131701H 6K0131701N</p> <p><b>46.6017</b> 6K9253409 6K9253409D 6K9253409F</p> <p><b>46.7023</b> 6K9253609 6K9253609A</p>	<p><b>INCA</b> </p> <p><b>1.4 i</b></p> <p>From 11/1995 To 2000</p> <p><b>c.c.</b> 1390 <b>Kw.</b> 44 <b>Hp.</b> 60</p>
<p><b>46.0017</b> 6K0253060GX</p> <p><b>46.6017</b> 6K9253409 6K9253409D 6K9253409F</p> <p><b>46.7023</b> 6K9253609 6K9253609A</p>	<p><b>INCA</b> </p> <p><b>1.4 i</b></p> <p>From 03/2000 To 01/2004</p> <p><b>c.c.</b> 1390 <b>Kw.</b> 44 <b>Hp.</b> 60</p>

<p><b>INCA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.6 i</b></p> <p>From 11/1995 To 09/2000</p> <p><b>c.c.</b> 1595-1598  <b>Kw.</b> 55  <b>Hp.</b> 75</p>	 <p><b>58.0031</b> 6K0253085BV 6K0253085BX</p> <p><b>46.6018</b> 6K9253409A</p> <p><b>46.7023</b> 6K9253609 6K9253609A</p> <p style="text-align: right;">ART2285</p>
<p><b>INCA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.6 i</b></p> <p>From 06/1997 To 02/2000</p> <p><b>c.c.</b> 1595  <b>Kw.</b> 55  <b>Hp.</b> 75</p>	 <p><b>46.1015</b> 6K0253087G</p> <p><b>58.0001</b> 191131701D 6K0131701H 6K0131701N 6N0131701HV 191131701DV</p> <p><b>46.6017</b> 6K9253409 6K9253409D 6K9253409F</p> <p><b>46.7023</b> 6K9253609 6K9253609A</p> <p style="text-align: right;">ART2287</p>
<p><b>INCA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.9 D</b></p> <p>From 11/1995 To 02/2000</p> <p><b>c.c.</b> 1896  <b>Kw.</b> 47  <b>Hp.</b> 64</p>	 <p><b>58.1033</b> 6K0253091H</p> <p><b>58.0017</b> 6K0131701LX 6K0131701LV</p> <p><b>46.6017</b> 6K9253409 6K9253409D 6K9253409F</p> <p><b>46.7023</b> 6K9253609 6K9253609A</p> <p style="text-align: right;">ART2289</p>
<p><b>INCA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.9 i SDi</b></p> <p>From 11/1995 To</p> <p><b>c.c.</b> 1896  <b>Kw.</b> 47  <b>Hp.</b> 64</p>	 <p><b>58.1033</b> 6K0253091H</p> <p><b>58.0005</b> 6K0131701E 028131701BX 028131701B 1015983 028131089X</p> <p><b>58.6037</b> 6K9253409B</p> <p><b>58.7007</b> 6K9253609B</p> <p style="text-align: right;">ART2291</p>
<p><b>LEON</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.4 i</b></p> <p> Hatchback</p> <p>From 09/1999 To 06/2005</p> <p><b>c.c.</b> 1390  <b>Kw.</b> 55  <b>Hp.</b> 75</p> <p>Mot. AKW-APE</p>	 <p><b>58.1029</b> 1J02530191CC 1J0253091DD</p> <p><b>58.0022</b> 1J131089BX</p> <p><b>04.6019</b> 1J0253209E</p> <p><b>58.7019</b> 1J62553609R 1J6253609AK</p> <p style="text-align: right;">ART2295</p>











 <p><b>04.0012</b> 1J0253058KX 1J0253058X 1J0253058KV 1J0253058TX</p> <p><b>04.6019</b> 1J0253209</p> <p><b>04.7016</b> 1J6253609C 1J6253609AA</p> <p>ART2378</p>	<p><b>LEON</b> </p> <p><b>1.6</b></p> <p> Hatchback From 09/1999 To 06/2005 c.c. 1595 Kw. 74 Hp. 101 Mot. AEH-AKL</p>
 <p><b>04.0013</b> 1J0253058MX</p> <p><b>04.6020</b> 1J0253209B</p> <p><b>04.7017</b> 1J6253609H 1M6253609 1M6253609M</p> <p>ART2379</p>	<p><b>LEON</b> </p> <p><b>1.8 20V</b></p> <p> Hatchback From 09/1999 To c.c. 1781 Kw. 92 Hp. 125 Mot. AGN</p>
 <p><b>58.0024</b> 1J1253058CX</p> <p><b>04.6019</b> 1J0253209E</p> <p><b>04.7016</b> 1J6253609AA</p> <p>ART2296</p>	<p><b>LEON</b> </p> <p><b>1.9 SDi</b></p> <p> Hatchback From 09/1999 To 10/2003 c.c. 1896 Kw. 50 Hp. 68 Mot. AQM</p>
 <p><b>04.0015</b> 1J0253208AX 1J0253058HX</p> <p><b>04.5006</b> 1J0253201</p> <p><b>04.7019</b> 1J6253609L 1J6253609BA</p> <p>ART2377</p>	<p><b>LEON</b> </p> <p><b>1.9 TDi</b></p> <p> Hatchback From 10/1998 To 10/2005 c.c. 1896 Kw. 66 Hp. 90 Mot. AGR</p>
 <p><b>04.0038</b> 1J0253208NX 1J0253058GX</p> <p><b>04.5006</b> 1J0253201</p> <p><b>04.7019</b> 1J6253609L</p> <p>ART2376</p>	<p><b>LEON</b> </p> <p><b>1.9 TDi</b></p> <p> Hatchback From 10/1998 To 10/2005 c.c. 1896 Kw. 66-81-91 Hp. 90-110-130 Mot. ALH-ASV-AHF</p>











# SEAT











<b>MALAGA</b> <b>1.2 - 1.5</b>  <b>Saloon</b> <b>From 05/1985 To 08/1989</b> <b>c.c.</b> 1193-1461 <b>Kw.</b> 46-63 <b>Hp.</b> 63-85	 <p><b>46.1004</b> SE021115103B</p> <p><b>46.6004</b> SE021115201C SE021115201F</p> <p><b>46.7007</b> SE023115315A SE023115315B</p> <p>ART2329</p>
<b>MALAGA</b> <b>1.2 i - 1.5 i</b>  <b>Saloon</b> <b>From 07/1989 To 06/1991</b> <b>c.c.</b> 1193-1461 <b>Kw.</b> 44-63 <b>Hp.</b> 60-85	 <p><b>46.1004</b> SE021115103B</p> <p><b>46.6004</b> SE021115201C SE021115201F</p> <p><b>46.7008</b> SE023115315D</p> <p>ART2330</p>
<b>MALAGA</b> <b>1.5 i</b>  <b>Saloon</b> <b>From 05/1985 To 09/1989</b> <b>c.c.</b> 1461 <b>Kw.</b> 74 <b>Hp.</b> 100	 <p><b>46.2001</b> SE021115103F</p> <p><b>46.6004</b> SE021115201G SE021115201H</p> <p><b>46.7007</b> SE023115315B SE023115315C</p> <p>ART2331</p>
<b>MALAGA</b> <b>1.5 i</b>  <b>Saloon</b> <b>From 10/1989 To 06/1991</b> <b>c.c.</b> 1461 <b>Kw.</b> 74 <b>Hp.</b> 100	 <p><b>46.2001</b> SE021115103F</p> <p><b>46.6004</b> SE021115201G SE021115201H</p> <p><b>46.7008</b> SE023115315E</p> <p>ART2333</p>
<b>MALAGA</b> <b>1.7 D</b>  <b>Saloon</b> <b>From 07/1985 To 06/1989</b> <b>c.c.</b> 1714 <b>Kw.</b> 40 <b>Hp.</b> 54	 <p><b>46.1005</b> SE138115103A</p> <p><b>46.6005</b> SE021115201B</p> <p><b>46.7007</b> SE023115315A SE023115315B</p> <p><b>46.1008</b> ← 7 / 1986 → 1988 SE021115103D</p> <p>ART2334</p>

 <p><b>46.1008</b> SE021115103D</p> <p><b>46.6005</b> SE021115201B</p> <p><b>46.7008</b> SE023115315E SE023115315D</p> <p>ART2335</p>	<p><b>MALAGA</b></p> <p><b>1.7 D</b></p> <p> <b>Saloon</b></p> <p><b>From 10/1989 To 10/1992</b></p> <p><b>c.c.</b> 1714 <b>Kw.</b> 42 <b>Hp.</b> 57</p>
 <p><b>46.1014</b> SE028115104A</p> <p><b>46.7010</b> SE028115303A</p> <p>ART2332</p>	<p><b>MARBELLA</b></p> <p><b>0.8 - 0.9</b></p> <p> <b>Hatchback</b></p> <p><b>From 08/1986 To 07/1992</b></p> <p><b>c.c.</b> 843-903 <b>Kw.</b> 25-29 <b>Hp.</b> 34-40 4 Gear</p>
 <p><b>46.1006</b> SE028115104B</p> <p><b>46.7010</b> SE028115303A</p> <p>ART2343</p>	<p><b>MARBELLA</b></p> <p><b>0.8 - 0.9</b></p> <p> <b>Hatchback</b></p> <p><b>From 08/1986 To 07/1992</b></p> <p><b>c.c.</b> 843-903 <b>Kw.</b> 25-29 <b>Hp.</b> 34-40 5 Gear</p>
 <p><b>46.0001</b> 6A0253208B</p> <p><b>46.5001</b> 6A0253609B</p> <p><b>46.7010</b> SE028115303A</p> <p>ART2350</p>	<p><b>MARBELLA</b> </p> <p><b>0.9</b></p> <p> <b>Hatchback</b></p> <p><b>From 01/1987 To 11/1996</b></p> <p><b>c.c.</b> 903 <b>Kw.</b> 29 <b>Hp.</b> 40</p>
 <p><b>46.1002</b> 3936289</p> <p><b>46.6001</b> 3936292</p> <p><b>12.7063</b> 4401369</p> <p>ART2301</p>	<p><b>RONDA</b></p> <p><b>1.2</b></p> <p> <b>Hatchback</b></p> <p><b>From 06/1983 To 05/1984</b></p> <p><b>c.c.</b> 1193 <b>Kw.</b> 47 <b>Hp.</b> 64</p>














# SEAT

<div><b>RONDA</b></div> <div>1.2</div> <div></div> <div>Hatchback</div> <div>From 05/1984 To 09/1984</div> <div>c.c. 1193</div> <div>Kw. 47</div> <div>Hp. 64</div>	 <p>46.1002 3936289</p> <p>46.6001 3936292</p> <p>46.7001 3940048</p> <p>ART2302</p>
<div><b>RONDA</b></div> <div>1.2 - 1.5</div> <div></div> <div>Hatchback</div> <div>From 05/1984 To 11/1984</div> <div>c.c. 1193-1461</div> <div>Kw. 44-47-63</div> <div>Hp. 60-64-85</div>	 <p>46.1003 SE021115103A</p> <p>46.6003 SE021115201A</p> <p>46.7003 SE022115315A</p> <p>ART2303</p>
<div><b>RONDA</b></div> <div>1.2 - 1.5</div> <div></div> <div>Hatchback</div> <div>From 12/1984 To 12/1986</div> <div>c.c. 1193-1461</div> <div>Kw. 44-47-63</div> <div>Hp. 60-64-85</div>	 <p>46.1004 SE021115103B</p> <p>46.6004 SE021115201C</p> <p>46.7003 SE022115315A</p> <p>ART2304</p>
<div><b>RONDA</b></div> <div>1.7 D</div> <div></div> <div>Hatchback</div> <div>From 06/1983 To 05/1984</div> <div>c.c. 1714</div> <div>Kw. 40</div> <div>Hp. 54-55</div>	 <p>12.1057 4431966</p> <p>12.6024 4436948</p> <p>12.7063 4401369</p> <p>ART2305</p>
<div><b>RONDA</b></div> <div>1.7 D</div> <div></div> <div>Hatchback</div> <div>From 05/1984 To 11/1984</div> <div>c.c. 1714</div> <div>Kw. 40</div> <div>Hp. 54</div>	 <p>12.1057 4431966</p> <p>12.6024 4436948</p> <p>46.7001 3940048</p> <p>ART2306</p>

 <p><b>46.1005</b> SE138115103A</p> <p><b>46.6005</b> SE021115201B</p> <p><b>46.7003</b> SE022115315A</p> <p>ART2307</p>	<p><b>RONDA</b></p> <p><b>1.7 D</b></p> <p> Hatchback</p> <p>From 06/1984 To 12/1987</p> <p><b>c.c.</b> 1714</p> <p><b>Kw.</b> 40</p> <p><b>Hp.</b> 54</p>
 <p><b>46.1014</b> SE028115104A</p> <p><b>46.7012</b> SE029115303A</p> <p>ART2359</p>	<p><b>TERRA</b></p> <p><b>0.9</b></p> <p> Stationwagon-Van</p> <p>From 01/1987 To 12/1989</p> <p><b>c.c.</b> 903</p> <p><b>Kw.</b> 29</p> <p><b>Hp.</b> 40</p> <p>4 Gear</p>
 <p><b>46.1006</b> SE028115104B</p> <p><b>46.7012</b> SE029115303A</p> <p>ART2369</p>	<p><b>TERRA</b></p> <p><b>0.9</b></p> <p> Stationwagon-Van</p> <p>From 01/1987 To 12/1989</p> <p><b>c.c.</b> 903</p> <p><b>Kw.</b> 29</p> <p><b>Hp.</b> 40</p> <p>5 Gear</p>
 <p><b>46.1020</b> SE029115199B</p> <p><b>46.6007</b> SE029115299A</p> <p><b>46.7014</b> SE029115399A</p> <p>ART2282</p>	<p><b>TERRA</b></p> <p><b>0.9</b></p> <p> Stationwagon-Van</p> <p>From 1990 To 07/1992</p> <p><b>c.c.</b> 903</p> <p><b>Kw.</b> 29</p> <p><b>Hp.</b> 40</p> <p>5 Gear</p>
 <p><b>46.1018</b> SE029115199C</p> <p><b>46.6007</b> SE029115299A</p> <p><b>46.7014</b> SE029115399A</p> <p>ART2380</p>	<p><b>TERRA</b></p> <p><b>0.9</b></p> <p> Stationwagon-Van</p> <p>From 1990 To 1992</p> <p><b>c.c.</b> 903</p> <p><b>Kw.</b> 29</p> <p><b>Hp.</b> 40</p> <p>4 Gear</p>

<p><b>TERRA</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>0.9</b></p> <p> Stationwagon-Van From 1990 To 12/1996 c.c. 903 Kw. 29 Hp. 40</p>	 <p><b>46.0001</b> 6A0253208A</p> <p><b>46.6006</b> 6D0253209</p> <p><b>46.7014</b> SE029115399A</p> <p style="text-align: right;">ART2297</p>
<p><b>TERRA</b></p> <p><b>1.3 D - 1.4 D</b></p> <p> Stationwagon-Van From 1989 To 12/1995 c.c. 1272-1398 Kw. 33-35 Hp. 45-48</p>	 <p><b>46.1022</b> SE029115199A</p> <p><b>46.6007</b> SE029115299A</p> <p><b>46.7014</b> SE029115399A</p> <p style="text-align: right;">ART2300</p>
<p><b>TOLEDO I</b></p> <p><b>1.6 i</b></p> <p> Hatchback From 05/1991 To 10/1993 c.c. 1595 Kw. 54 Hp. 73</p>	 <p><b>58.1028</b> 191253091AQ</p> <p><b>46.6009</b> 1L0253409B</p> <p><b>46.7016</b> 1L0253609C</p> <p style="text-align: right;">ART2342</p>
<p><b>TOLEDO I</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.6 i</b></p> <p> Hatchback From 05/1991 To 12/1996 c.c. 1595 Kw. 52-55 Hp. 71-75</p>	 <p><b>58.1009</b> 191253091AP</p> <p><b>58.0006</b> 1L0253212 165131701F</p> <p><b>46.6008</b> 1L0253409C</p> <p><b>46.7016</b> 1L0253609C</p> <p style="text-align: right;">ART2344</p>
<p><b>TOLEDO I</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.8 i GT 16V</b></p> <p> Hatchback From 05/1991 To 03/1995 c.c. 1781 Kw. 92-98 Hp. 125-133</p>	 <p><b>58.1011</b> 191253091T 357253091E 191253091M</p> <p><b>58.0007</b> 165131701E</p> <p><b>58.6024</b> 1L0253209J</p> <p><b>58.6026</b> 1L0253409A</p> <p><b>46.7020</b> 1L0253609 1L0253609N</p> <p style="text-align: right;">ART2346</p>

<p><b>58.1009</b> 191253091AP</p> <p><b>58.0006</b> 1L0253212 165131701F</p> <p><b>46.6012</b> 1L0253409D</p> <p><b>46.7018</b> 1L0253609D</p> <p>ART2345</p>	<p><b>TOLEDO I</b> </p> <p><b>1.8 i</b></p> <p> Hatchback From 05/1991 To 12/1996 c.c. 1781 Kw. 65 Hp. 88</p>
<p><b>46.1026</b> 1L0253091</p> <p><b>46.6008</b> 1L0253409C</p> <p><b>46.7016</b> 1L0253609C</p> <p>ART2348</p>	<p><b>TOLEDO I</b></p> <p><b>1.9 D</b></p> <p> Hatchback From 05/1991 To 10/1993 c.c. 1896 Kw. 50 Hp. 68</p>
<p><b>58.1048</b> 1H0253087AC</p> <p><b>58.0005</b> 6K0131701E</p> <p><b>46.6012</b> 1L0253409D</p> <p><b>46.7018</b> 1L0253609D</p> <p>ART2349</p>	<p><b>TOLEDO I</b> </p> <p><b>1.9 TD</b></p> <p> Hatchback From 06/1994 To 04/1997 c.c. 1896 Kw. 55 Hp. 75</p>
<p><b>58.1011</b> 191253091T 357253091E</p> <p><b>58.0007</b> 165131701E</p> <p><b>46.6011</b> 1L0253209B</p> <p><b>46.6016</b> 1L0253409</p> <p><b>46.7020</b> 1L0253609</p> <p>ART2347</p>	<p><b>TOLEDO I</b> </p> <p><b>2.0 i GT</b></p> <p> Hatchback From 05/1991 To 1993 c.c. 1984 Kw. 110 Hp. 150</p>
<p><b>58.1019</b> 1J0253091CC</p> <p><b>58.0022</b> 1J0131089BX</p> <p><b>04.6019</b> 1J0253209G</p> <p><b>58.7017</b> 1J525309AC 1J5253609P</p> <p>ART2364</p>	<p><b>TOLEDO II</b> </p> <p><b>1.4 16V</b></p> <p>  Saloon-Stationwagon From 09/1998 To 05/2002 c.c. 1390 Kw. 55 Hp. 75</p>

<p><b>TOLEDO II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.6 i</b></p> <p> </p> <p><b>Saloon-Stationwagon</b>  <b>From 10/1998 To 05/2005</b>  <b>c.c.</b> 1595  <b>Kw.</b> 74-75  <b>Hp.</b> 100-101</p>	 <p><b>04.0012</b> 1J0253058KX</p> <p><b>04.6019</b> 1J0253209</p> <p><b>58.7046</b> 1J5253609C 1J5253609S</p> <p style="text-align: right;">ART2365</p>
<p><b>TOLEDO II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.8 i 20V</b></p> <p></p> <p><b>Saloon</b>  <b>From 10/1998 To 10/2005</b>  <b>c.c.</b> 1781  <b>Kw.</b> 85-92  <b>Hp.</b> 115-125</p>	 <p><b>04.0013</b> 1J0253058MX</p> <p><b>04.6020</b> 1J0253209B</p> <p><b>50.7010</b> 1J5253609H</p> <p style="text-align: right;">ART2366</p>
<p><b>TOLEDO II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.9 TDi</b></p> <p> </p> <p><b>Saloon-Stationwagon</b>  <b>From 10/1998 To 05/2005</b>  <b>c.c.</b> 1896  <b>Kw.</b> 81-85  <b>Hp.</b> 110-115  <b>Mot.</b> ALH</p>	 <p><b>04.0038</b> 1J0253208NX</p> <p><b>04.5006</b> 1J0253201</p> <p><b>50.7009</b> 1J5253609L</p> <p style="text-align: right;">ART2370</p>
<p><b>TOLEDO II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>1.9 TDi</b></p> <p> </p> <p><b>Saloon-Stationwagon</b>  <b>From 10/1998 To 05/2005</b>  <b>c.c.</b> 1896  <b>Kw.</b> 66-81-96  <b>Hp.</b> 90-110-130  <b>Mot.</b> AGR-ASV-AHF</p>	 <p><b>58.0025</b> 1J0253058MX</p> <p><b>04.5006</b> 1J0253201</p> <p><b>50.7009</b> 1J5253609L</p> <p style="text-align: right;">ART2368</p>
<p><b>TOLEDO II</b> <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">KAT</span></p> <p><b>2.3 i V5</b></p> <p></p> <p><b>Saloon</b>  <b>From 10/1998 To 05/2001</b>  <b>c.c.</b> 2324  <b>Kw.</b> 110  <b>Hp.</b> 150</p>	 <p><b>04.6021</b> 1J0253209C</p> <p><b>50.7009</b> 1J5253609Q</p> <p style="text-align: right;">ART2367</p>



**12.1012**  
4153029

**12.6012**  
4168233  
4181165

**12.7025**  
4275294  
4308517

**124**

**PAMPLONA**



**Saloon**

**From 1976 To 1980**

**c.c.** 1438

**Kw.** 51-55

**Hp.** 70-75

ART2323