





































































 <p><b>44.0005</b> 4878682</p> <p><b>44.4002</b> 4750741</p> <p><b>44.6008</b> 4960936</p> <p><b>44.7006</b> 4896254 4528287</p> <p>ART2241</p>	<p><b>9-3</b> <span style="float: right;">(KAT)</span></p> <p><b>2.0 i 16V</b></p> <p></p> <p>Hatchback-Cabrio-Coupe</p> <p>From 1998 To 10/2000</p> <p><b>c.c.</b> 1985</p> <p><b>Kw.</b> 96</p> <p><b>Hp.</b> 131</p>
 <p><b>44.0006</b> 4623104</p> <p><b>44.4002</b> 4750741</p> <p><b>44.6008</b> 4960936</p> <p><b>44.7007</b> 4904801</p> <p>ART2242</p>	<p><b>9-3</b> <span style="float: right;">(KAT)</span></p> <p><b>2.0 i T 16V</b></p> <p></p> <p>Hatchback-Cabrio-Coupe</p> <p>From 1998 To 2003</p> <p><b>c.c.</b> 1985</p> <p><b>Kw.</b> 113-136-147</p> <p><b>Hp.</b> 154-185-200</p>
 <p><b>44.0005</b> 4878682</p> <p><b>44.4002</b> 4750741</p> <p><b>44.6008</b> 4960936</p> <p><b>44.7006</b> 4896254</p> <p>ART2243</p>	<p><b>9-3</b> <span style="float: right;">(KAT)</span></p> <p><b>2.3 i</b></p> <p></p> <p>Hatchback-Cabrio-Coupe</p> <p>From 1998 To 2000</p> <p><b>c.c.</b> 2290</p> <p><b>Kw.</b> 110</p> <p><b>Hp.</b> 150</p>
 <p><b>44.0007</b> 4965885</p> <p><b>44.4003</b> 4898037</p> <p><b>44.6013</b> 5300714 4753745</p> <p><b>44.7013</b> 4966925 5321625</p> <p>ART2248</p>	<p><b>9-5</b> <span style="float: right;">(KAT)</span></p> <p><b>2.0 T 16V</b></p> <p></p> <p>Saloon-Stationwagon</p> <p>From 1997 To 06/2005</p> <p><b>c.c.</b> 1985</p> <p><b>Kw.</b> 110-125</p> <p><b>Hp.</b> 150-170</p>
 <p><b>44.0008</b> 5325519</p> <p><b>44.4003</b> 4898037</p> <p><b>44.6013</b> 5322714 4753745</p> <p><b>44.7013</b> 4966925 5321625</p> <p>ART2247</p>	<p><b>9-5</b> <span style="float: right;">(KAT)</span></p> <p><b>2.0 T 16V</b></p> <p></p> <p>Saloon-Stationwagon</p> <p>From 09/2000 To 08/2005</p> <p><b>c.c.</b> 1985</p> <p><b>Kw.</b> 110</p> <p><b>Hp.</b> 150</p>
















<p><b>9-5</b> <span style="float: right;">(KAT)</span></p> <p><b>2.3 T 16V</b></p> <p> </p> <p><b>Saloon-Stationwagon</b>  <b>From 10/1999 To 08/2005</b>  <b>c.c.</b> 2290  <b>Kw.</b> 169  <b>Hp.</b> 230</p>	 <p><b>44.0007</b> 4965885</p> <p><b>44.4003</b> 4898037</p> <p><b>44.6013</b> 5322714</p> <p><b>44.7013</b> 4966925</p> <p style="text-align: right;">ART2246</p>
<p><b>99</b></p> <p><b>2.0</b></p> <p></p> <p><b>Saloon</b>  <b>From 09/1974 To 12/1984</b>  <b>c.c.</b> 1985  <b>Kw.</b> 74-79-87  <b>Hp.</b> 100-108-118</p>	 <p><b>44.1002</b> 7894751</p> <p><b>44.2001</b> 7894736</p> <p><b>44.6001</b> 7533631 7533623</p> <p><b>44.9001</b> 9396375</p> <p style="text-align: right;">ART2244</p>
<p><b>99</b></p> <p><b>2.0</b></p> <p></p> <p><b>Hatchback</b>  <b>From 1976 To 1980</b>  <b>c.c.</b> 1985  <b>Kw.</b> 74-79-87  <b>Hp.</b> 100-108-118</p>	 <p><b>44.1002</b> 7894751</p> <p><b>44.2001</b> 7894736</p> <p><b>44.6001</b> 7533631 7533623</p> <p><b>44.9002</b> 9317405</p> <p style="text-align: right;">ART2249</p>
<p><b>900</b></p> <p><b>2.0</b></p> <p> </p> <p><b>Saloon-Hatchback</b>  <b>From 09/1978 To 1982</b>  <b>c.c.</b> 1985  <b>Kw.</b> 74-79-87  <b>Hp.</b> 100-108-118</p>	 <p><b>44.1003</b> 789469</p> <p><b>44.2001</b> 7894736</p> <p><b>44.6001</b> 7533631 7533623</p> <p><b>44.9002</b> 9317405</p> <p style="text-align: right;">ART2250</p>
<p><b>900</b></p> <p><b>2.0</b></p> <p> </p> <p><b>Saloon-Hatchback</b>  <b>From 1983 To 1984</b>  <b>c.c.</b> 1985  <b>Kw.</b> 74-79-85  <b>Hp.</b> 100-108-115</p>	 <p><b>44.1003</b> 789469</p> <p><b>44.2001</b> 7894736</p> <p><b>44.6001</b> 7533631 7533623</p> <p><b>44.9003</b> 9365727</p> <p style="text-align: right;">ART2251</p>









 <p><b>44.2005</b> 9300740</p> <p><b>44.6002</b> 8336034 9326463 9365511</p> <p><b>44.9005</b> 9303222</p> <p>ART2253</p>	<p><b>900</b> <b>2.0 Turbo</b></p> <p> <b>Saloon</b> <b>From 10/1978 To 10/1980</b> <b>c.c.</b> 1985 <b>Kw.</b> 107 <b>Hp.</b> 146</p>
 <p><b>44.2007</b> 8822306 9363649</p> <p><b>44.6002</b> 8336034 9326463 9365511</p> <p><b>44.9006</b> 9332503</p> <p>ART2254</p>	<p><b>900</b> <b>2.0 Turbo</b></p> <p>  <b>Saloon-Hatchback</b> <b>From 10/1980 To 1982</b> <b>c.c.</b> 1985 <b>Kw.</b> 107 <b>Hp.</b> 145</p>
 <p><b>44.2007</b> 8822306 9363649</p> <p><b>44.6002</b> 8336034 9326463 9365511</p> <p><b>44.9007</b> 9365735</p> <p>ART2221</p>	<p><b>900</b> <b>2.0 Turbo</b></p> <p> <b>Saloon</b> <b>From 1983 To 1984</b> <b>c.c.</b> 1985 <b>Kw.</b> 107 <b>Hp.</b> 146</p>
 <p><b>44.2009</b> 7527385</p> <p><b>44.6003</b> 9349143</p> <p><b>44.7001</b> 7536196</p> <p>ART2222</p>	<p><b>900</b> <b>2.0 i</b></p> <p>  <b>Saloon-Hatchback</b> <b>From 10/1984 To 09/1985</b> <b>c.c.</b> 1985 <b>Kw.</b> 74-85 <b>Hp.</b> 100-115</p>
 <p><b>44.2010</b> 7528078</p> <p><b>44.6003</b> 9349143</p> <p><b>44.7001</b> 7536196</p> <p>ART2223</p>	<p><b>900</b> <b>2.0 i</b></p> <p>  <b>Saloon-Hatchback</b> <b>From 10/1985 To 08/1990</b> <b>c.c.</b> 1985 <b>Kw.</b> 74-85 <b>Hp.</b> 100-115</p>

<p><b>900</b> <b>2.0 Turbo</b></p> <p> Hatchback-Cabrio-Coupe From 01/1984 To 09/1990 c.c. 1985 Kw. 103-110-129 Hp. 140-150-175</p>	 <p><b>44.2007</b> 8822306 9363649</p> <p><b>44.6004</b> 934192</p> <p><b>44.9009</b> 7535925 7512154</p> <p>ART2224</p>
<p><b>900 II</b> <span>(KAT)</span> <b>2.0 16V</b></p> <p> Hatchback From 08/1994 To 02/1998 c.c. 1985 Kw. 96-98 Hp. 131-133</p>	 <p><b>44.1008</b> 4444527</p> <p><b>44.0001</b> 4526968</p> <p><b>44.6008</b> 4226320</p> <p><b>44.7006</b> 4225751 4528287</p> <p>ART2230</p>
<p><b>900 II</b> <span>(KAT)</span> <b>2.0 16V Turbo</b></p> <p> Hatchback From 07/1993 To 02/1998 c.c. 1985 Kw. 136 Hp. 185</p>	 <p><b>44.0002</b> 4444204</p> <p><b>44.4001</b> 4445516</p> <p><b>44.6008</b> 4226320</p> <p><b>44.7007</b> 4225926</p> <p>ART2232</p>
<p><b>900 II</b> <span>(KAT)</span> <b>2.3 16V</b></p> <p> Hatchback From 07/1993 To 02/1998 c.c. 2290 Kw. 110 Hp. 150</p>	 <p><b>44.0003</b> 4445433</p> <p><b>44.4001</b> 4445516</p> <p><b>44.6008</b> 4226320</p> <p><b>44.7006</b> 4225751</p> <p>ART2234</p>
<p><b>900 II</b> <span>(KAT)</span> <b>2.5 V6 24V</b></p> <p> Hatchback-Cabrio-Coupe From 07/1993 To 02/1998 c.c. 2498 Kw. 125 Hp. 170</p>	 <p><b>44.6008</b> 4226320</p> <p><b>44.7012</b> 4235990 4228261</p> <p>ART2245</p>

 <p><b>44.1005</b> 9392929 4019535</p> <p><b>44.2002</b> 9381252</p> <p><b>44.6005</b> 9379041</p> <p><b>44.7002</b> 9373689 9393364</p> <p>ART2226</p>	<p><b>9000</b></p> <p><b>2.0 i 16V</b></p> <p> </p> <p>Hatchback-5P</p> <p>From 12/1985 To 09/1988</p> <p><b>c.c.</b> 1985</p> <p><b>Kw.</b> 94</p> <p><b>Hp.</b> 128</p>
 <p><b>44.1005</b> 9392929 4019535</p> <p><b>44.2002</b> 9381252</p> <p><b>44.6007</b> 8979650 8822249</p> <p><b>44.7009</b> 8822231 4162061 8979130</p> <p>ART2228</p>	<p><b>9000</b></p> <p><b>2.0 i 16V - 2.3 i 16V</b></p> <p> </p> <p>Hatchback-5P</p> <p>From 10/1988 To 10/1991</p> <p><b>c.c.</b> 1985-2290</p> <p><b>Kw.</b> 94-110</p> <p><b>Hp.</b> 128-150</p>
 <p><b>44.1005</b> 9392929 4019535</p> <p><b>44.2002</b> 9381252</p> <p><b>44.6007</b> 8979650 8822249</p> <p><b>44.7005</b> 8979155</p> <p>ART2227</p>	<p><b>9000</b></p> <p><b>2.0 i 16V - 2.3 i 16V</b></p> <p></p> <p>Saloon</p> <p>From 10/1988 To 10/1991</p> <p><b>c.c.</b> 1985-2290</p> <p><b>Kw.</b> 94-110</p> <p><b>Hp.</b> 128-150</p>
 <p><b>44.1006</b> 9393455</p> <p><b>44.0004</b> 9392457</p> <p><b>44.6007</b> 8979650</p> <p><b>44.7009</b> 8822231 4162061 8979130</p> <p>ART2231</p>	<p><b>9000</b> </p> <p><b>2.0 i 16V - 2.3 i 16V</b></p> <p> </p> <p>Hatchback-5P</p> <p>From 10/1988 To 10/1991</p> <p><b>c.c.</b> 1985-2290</p> <p><b>Kw.</b> 94-110</p> <p><b>Hp.</b> 128-150</p>
 <p><b>44.1006</b> 9393455</p> <p><b>44.0004</b> 9392457</p> <p><b>44.6007</b> 8979650 8822249</p> <p><b>44.7005</b> 8979155</p> <p>ART2229</p>	<p><b>9000</b> </p> <p><b>2.0 i 16V - 2.3 i 16V</b></p> <p></p> <p>Saloon</p> <p>From 10/1988 To 10/1991</p> <p><b>c.c.</b> 1985-2290</p> <p><b>Kw.</b> 94-110</p> <p><b>Hp.</b> 128-150</p>

<div>9000</div> <div>2.0 i 16V - 2.3 i 16V</div> <div><div><div></div><div>5</div></div><div>Hatchback-5P</div></div> <div>From 10/1991 To 10/1992</div> <div>c.c. 1985-2290</div> <div>Kw. 94-110</div> <div>Hp. 128-150</div> <div>KAT</div>	 <div><div>44.1006</div><div>9393455</div><div>44.0004</div><div>9392457</div><div>44.6010</div><div>4018867 4391421 5324942</div><div>44.7009</div><div>8822231 4162061 8979130</div></div> <div>ART3070</div>
<div>9000</div> <div>2.0 i 16V - 2.3 i 16V</div> <div><div><div></div><div></div></div><div>Saloon</div></div> <div>From 10/1991 To 10/1992</div> <div>c.c. 1985-2290</div> <div>Kw. 94-110</div> <div>Hp. 128-150</div> <div>KAT</div>	 <div><div>44.1006</div><div>9393455</div><div>44.0004</div><div>9392457</div><div>44.6010</div><div>4018867 4391421 5324942</div><div>44.7005</div><div>8979155</div></div> <div>ART2235</div>
<div>9000</div> <div>2.0 i 16V - 2.3 i 16V</div> <div><div><div></div><div>5</div></div><div>Hatchback-5P</div></div> <div>From 10/1992 To 10/1993</div> <div>c.c. 1985-2290</div> <div>Kw. 94-110</div> <div>Hp. 128-150</div> <div>KAT</div>	 <div><div>44.1010</div><div>4163911</div><div>44.0004</div><div>9392457</div><div>44.6010</div><div>4018867 4391421 5324942</div><div>44.7009</div><div>8822231 4162061 8979130</div></div> <div>ART2239</div>
<div>9000</div> <div>2.0 i 16V - 2.3 i 16V</div> <div><div><div></div><div></div></div><div>Saloon</div></div> <div>From 10/1992 To 10/1993</div> <div>c.c. 1985-2290</div> <div>Kw. 94-110</div> <div>Hp. 128-150</div> <div>KAT</div>	 <div><div>44.1010</div><div>4163911</div><div>44.0004</div><div>9392457</div><div>44.6010</div><div>4018867 4391421 5324942</div><div>44.7005</div><div>8979155</div></div> <div>ART2240</div>
<div>9000</div> <div>2.0 i 16V - 2.3 i 16V</div> <div><div><div></div><div>5</div></div><div>Hatchback-5P</div></div> <div>From 10/1993 To 12/1997</div> <div>c.c. 1985-2290</div> <div>Kw. 94-110</div> <div>Hp. 128-150</div> <div>KAT</div>	 <div><div>44.1009</div><div>4442166</div><div>44.0004</div><div>9392457</div><div>44.6010</div><div>4018867 4391421 5324942</div><div>44.7009</div><div>8822231 4162061 8979130</div></div> <div>ART3071</div>

 <p><b>44.1009</b> 4442166</p> <p><b>44.0004</b> 9392457</p> <p><b>44.6010</b> 4018867 4391421 5324942</p> <p><b>44.7005</b> 8979155</p> <p>ART2238</p>	<p><b>9000</b> </p> <p><b>2.0 i 16V - 2.3 i 16V</b></p> <p> <b>Saloon</b></p> <p><b>From 10/1993 To 12/1997</b></p> <p><b>c.c.</b> 1985-2290</p> <p><b>Kw.</b> 94-110</p> <p><b>Hp.</b> 125-150</p>
 <p><b>44.1007</b> 9389560 8982688</p> <p><b>44.2003</b> 9389784 7539927</p> <p><b>44.6009</b> 9379124 8979700</p> <p><b>44.7011</b> 9393307</p> <p>ART2236</p>	<p><b>9000</b></p> <p><b>2.0 i T 16V</b></p> <p> <b>Hatchback-5P</b> </p> <p><b>From 1985 To 1988</b></p> <p><b>c.c.</b> 1985</p> <p><b>Kw.</b> 129</p> <p><b>Hp.</b> 175</p>
 <p><b>44.1007</b> 9389560 8982688</p> <p><b>44.2003</b> 9389784 7539927</p> <p><b>44.6009</b> 9379124 8979700</p> <p><b>44.7010</b> 9393349</p> <p>ART2237</p>	<p><b>9000</b></p> <p><b>2.0 i T 16V</b></p> <p> <b>Saloon</b></p> <p><b>From 1985 To 1988</b></p> <p><b>c.c.</b> 1985</p> <p><b>Kw.</b> 129</p> <p><b>Hp.</b> 175</p>
 <p><b>44.1011</b> 4020798</p> <p><b>44.0004</b> 9392457</p> <p><b>44.6007</b> 8979650 8822249</p> <p><b>44.7015</b> 4159976 5325006 8980542</p> <p>ART3072</p>	<p><b>9000</b> </p> <p><b>2.0 i T 16V - 2.3 i T 16V</b></p> <p> <b>Hatchback-5P</b> </p> <p><b>From 05/1988 To 10/1991</b></p> <p><b>c.c.</b> 1985-2290</p> <p><b>Kw.</b> 121-143</p> <p><b>Hp.</b> 165-194</p>
 <p><b>44.1011</b> 4020798</p> <p><b>44.0004</b> 9392457</p> <p><b>44.6007</b> 8979650 8822249</p> <p><b>44.7003</b> 8979163</p> <p>ART3073</p>	<p><b>9000</b> </p> <p><b>2.0 i T 16V - 2.3 i T 16V</b></p> <p> <b>Saloon</b></p> <p><b>From 05/1988 To 10/1991</b></p> <p><b>c.c.</b> 1985-2290</p> <p><b>Kw.</b> 121-143</p> <p><b>Hp.</b> 165-194</p>

<div>9000</div> <div>2.0 i T 16V - 2.3 i T 16V</div> <div><div><div></div><div>5</div></div><div>Hatchback-5P</div></div> <div>From 10/1989 To 10/1991</div> <div>c.c. 1985-2290</div> <div>Kw. 129-143</div> <div>Hp. 175-194</div>	<div></div> <div><div>44.1007</div><div>9389560 8982688</div></div> <div><div>44.2003</div><div>9389784 7539927</div></div> <div><div>44.6007</div><div>8979650 8822249</div></div> <div><div>44.7015</div><div>4159976 5325006 8980542</div></div> <div>ART2225</div>
<div>9000</div> <div>2.0 i T 16V - 2.3 i T 16V</div> <div><div><div></div><div></div></div><div>Saloon</div></div> <div>From 10/1989 To 10/1991</div> <div>c.c. 1985-2290</div> <div>Kw. 129-143</div> <div>Hp. 175-194</div>	<div></div> <div><div>44.1007</div><div>9389560 8982688</div></div> <div><div>44.2003</div><div>9389784 7539927</div></div> <div><div>44.6007</div><div>8979650 8822249</div></div> <div><div>44.7003</div><div>8979163</div></div> <div>ART3074</div>
<div>9000</div> <div>2.0 i T 16V - 2.3 i T 16V</div> <div><div><div></div><div>5</div></div><div>Hatchback-5P</div></div> <div>From 10/1991 To 1997</div> <div>c.c. 1985-2290</div> <div>Kw. 121-143</div> <div>Hp. 165-194</div> <div>KAT</div>	<div></div> <div><div>44.1011</div><div>4020798</div></div> <div><div>44.0004</div><div>9392457</div></div> <div><div>44.6010</div><div>4391421 4018067 5324942</div></div> <div><div>44.7015</div><div>4159976 5325006 8980542</div></div> <div>ART3075</div>
<div>9000</div> <div>2.0 i T 16V - 2.3 i T 16V</div> <div><div><div></div><div></div></div><div>Saloon</div></div> <div>From 10/1991 To 1997</div> <div>c.c. 1985-2290</div> <div>Kw. 121-143</div> <div>Hp. 165-194</div> <div>KAT</div>	<div></div> <div><div>44.1011</div><div>4020798</div></div> <div><div>44.0004</div><div>9392457</div></div> <div><div>44.6010</div><div>4391421 4018067 5324942</div></div> <div><div>44.7003</div><div>8979163</div></div> <div>ART3076</div>